

ARBORCOAT® WATERBORNE ULTRA FLAT SOLID STAIN K610

Features

- Beautiful rustic ultra flat finish
- Suitable for use on all types of wood and properly cured stucco, masonry, manufactured and fiber-cement siding
- Specially formulated to resist mildew growth on the coating
- Excellent touch up and re-coat properties
- Hides imperfections on exterior surfaces with an ultra-flat finish
- Easy to use with soap and water clean up

General Description

A premium ultra-flat solid stain which masks the grain of the wood without obscuring its texture. This durable finish protects and enhances the appearance of new or previously stained smooth or rough siding, manufactured hardboard and fiber-cement siding, shakes, trim, railings, fencing, stucco and masonry. The ultra flat finish minimizes exterior imperfections while maintaining excellent colour retention properties.

Recommended For

Residential or commercial applications where a premium quality finish is desired. Use on new or previously stained smooth or rough siding, manufactured hardboard and fibercement siding, shakes, trim, railings, fencing, stucco and masonry.

Limitations

- Do not apply when air and surface temperatures are below 4.4°C (40°F).
- · Do not apply to surfaces such as outdoor furniture or decks
- · Do not paint vinyl siding darker than the original colour

Product Information Colours: —Standard: **Pastel Base** Technical Data◊ White (1X) Vehicle Type 100% Acrylic Latex Pigment Type Titanium Dioxide Volume Solids Coverage per 3.79 L at —Tint Bases: 200 - 400 Sq. Ft. Recommended Film Thickness Benjamin Moore® Gennex® bases 1X, 2X, 3X, & 4X Recommended Film -Wet 5.3 mils Thickness - Dry 1.7 mils —Special Colours: Depending on surface texture and porosity. Be sure to estimate Contact your Benjamin Moore representative the right amount of paint for the job. This will ensure colour uniformity and minimize the disposal of excess paint. Certification: Dry Time @ 25°C To Touch 1 Hour (77°F) @ 50% RH To Recoat 3 - 4 Hours VOC compliant in all regulated areas. High humidity and cool temperatures will result in longer dry, recoat and service times. Master Painters Institute MPI #16 Evaporation, Coalescence Dries By 108 ± 2 KU Viscosity Flash Point None Gloss / Sheen Flat (1-5 @ 85°) 40°F - Min. Surface Temperature at Application Max 90°F **Technical Assistance** Thin With See Chart 1-800-361-5898, info@benjaminmoore.ca, www.benjaminmoore.ca Clean Up Thinner Clean Water Weight Per 3.79 L 11.43 lbs 40°F Min. Storage Temperature 90°F - Max **Volatile Organic Compounds (VOC)** 72.2 Grams/Liter .61 lbs./3.79 L

[♦] Reported values are for Pastel Base. Contact Benjamin Moore for values of other bases or colours.

Surface Preparation

Surfaces to be stained must be clean, dry and free of dirt, mildew, oil or grease. Remove contaminants or chalky residue from weathered painted surfaces by washing with Benjamin Moore® Clean Multi-Purpose Cleaner (K318). Excessive chalk must be removed by power wash equipment. Note: Smooth planed clapboards or siding must be sanded thoroughly or treated with Benjamin Moore® Brighten Brightener & Neutralizer (K317) to break the "mill glaze" to allow proper penetration and adhesion.

Mildew: Stains from mildew must be removed by cleaning with Benjamin Moore® Clean (K318) prior to coating the surface.

Painted Surfaces: Remove old scaling or peeling coatings by scraping, wire brushing and sanding. Glossy surfaces must be dulled by sanding. Un-weathered areas such as eaves, ceilings, or overhangs must be washed with a detergent solution and/or rinsed with a strong stream from a garden hose to remove surface salts that can interfere with proper adhesion.

Caution: Refer to the K317 and K318 technical data and material safety data sheets for instructions on their proper use and handling.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEÁD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS DAMAGE. ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by logging onto Health Canada @ http://www.hcsc.gc.ca/ewh-semt/contaminants/lead-

plomb/asked_questions-questions_posees-eng.php.

Primer/Finish Systems

Previously Stained, Painted, or Sealed Wood:

Primer: No priming necessary.

Finish: 1 or 2 coats Arborcoat® WB Ultra Flat Solid Stain.

New Wood or Properly Prepared Weathered Wood:

Primer: Priming usually unnecessary. If light shades are applied to wood with high tannin levels, such as redwood and cedar, 1 coat of Arborcoat® Oil Primer (366) should be used before top coating to prevent bleeding. If unsure, test a small area prior to staining.

Finish: 2 coats Arborcoat® WB Ultra Flat Solid Stain.

Stucco and Masonry:

Primer: No priming necessary if the surface is in good condition. Loose, sandy masonry should be hosed down thoroughly to remove surface particles, allowed to dry and primed with Super Spec® Masonry Interior / Exterior 100% Acrylic Masonry Sealer (N/066). New masonry must be cured unless primed with Super Spec® Masonry Interior / Exterior 100% Acrylic Masonry Sealer (N/066).

Finish: 1 or 2 coats Arborcoat® WB Ultra Flat Solid Stain.

Repaint, All Substrates: Prime bare areas with the primer recommended for the substrate above.

Application

Mixing of paint: Immediately prior to use, the paint should be mixed thoroughly even though it has been shaken mechanically by the retailer. Preferred application method is by brushing. Roller application should be done only on rough or textured surfaces. To minimize lapping, always maintain a wet edge. On horizontal siding apply the stain on a section of 2 or 3 boards completely across the house. Lower the ladder and continue in the same manner until the side is completed. Vertical siding is coated using the same principle from top to bottom. Never stop staining in midwall; continue until a natural break is reached, such as a window. Refrain from staining in direct hot sun. Do not apply when air and surface temperatures are below 4.4°C (40°F), nor over damp surfaces or during threatening weather.

This product can also be sprayed. The Chart below is for general application guidance.

Thinning/Cleaning

Conditioning with Benjamin Moore [®] 518 Extender may be necessary under certain conditions to adjust open time or spray characteristics. The chart below is for general guidance		
	Mild conditions	Severe conditions
	Humid (RH> 50%) with no direct sunlight & with little to no wind	Dry (RH<50%), in direct sunlight, or windy conditions
Brush: Nylon / Polyester	No thinning necessary	Add 518 Extender or
Roller : Aura [®] Roller Cover		water: Max of 8 fl. oz. to a 3.79 L of paint
Spray: Airless		Never add other paints or solvents.

Clean Up: Wash painting tools in warm soapy water immediately after use. Spray equipment should be given a final rinse with mineral spirits to prevent rusting.

Environmental Health & Safety Information

Use only in a well ventilated area. Keep container closed when not in use. In case of spillage, absorb with inert material and dispose of in accordance with local regulations. Wash thoroughly after handling.

KEEP OUT OF REACH OF CHILDREN PROTECT FROM FREEZING

Refer to Safety Data Sheet for additional health and safety information.