

Features

- Acrylic Latex Flat Paint
- Fast Drying
- Excellent Touch Up
- Excellent Hide
- Suitable for use in USDA • inspected facilities
- **Recommended For**

Professional grade paint for commercial and residential use on drywall, plaster, wood and masonry. Provides total hide in one coat and its flat finish lends to excellent touch-up in new construction and repaint work.

SUPER KOTE[®] 3000 LATEX HIGH BUILD FLAT **904 LINE**

General Description

Super Kote® 3000 Latex Hi-Build Flat is designed to provide total hide in one coat when applied to properly prepared interior surfaces. The flat sheen lends itself to excellent touchup. This product is an excellent choice for new construction as well as remedial work. Specifically formulated for professional spray application.

Limitations

- Apply only when surface and air temperatures are above • 50 °F (10 °C).
- Not for use in high abuse areas. ٠

		Product Informat		
Colors — Standard:			Technical Data◊	White
High Hide White			Vehicle Type	Acrylic
— Tint Bases:			Pigment Type	Titanium Dioxide
N/A			Volume Solids	34 ± 1.0%
			Coverage per Gallon at	
— Special Colors:			Recommended Film Thickness	
Contact your dealer.			Brush/Roller Spray Application	350 – 450 Sq. Ft
				150 – 250 Sq. Ft
Certifications & Qualifications: The products supported by this data sheet contain a maximum of 100 grams per liter VOC/VOS (0.82 lbs. /gal.) excluding water & exempt solvents.			Recommended Film Thickness (Brush/Roller) Recommended Film Thickness (Spray)	- Wet 3.6 to 4.6 mils - Drv 1.2 to 1.6 mils
				- Wet 6.5 to 10.0 mils
		– Dry 2.0 to 3.0 mils		
VOC REGION	COMPLIANT			texture and porosity. Be sure to unt of paint for the job. This will
FEDERAL	YES			and minimize the disposal of excess
отс	YES		paint.	
OTCII	NO		Dry Time @ 77 °F (25 °C) @ 50% RH	- Tack Free 30 Minutes
CARB	YES			– To Recoat 4 Hours
CARB07	NO	High humidity and cool temperatures will result in longe dry, recoat and service times.		
UTAH	NO		Dries By	Coalescence
AZMC	YES			
SCAQMD	NO		Viscosity	95 - 100 KU
			Flash Point	200 °F or greater (TT-P-141, Method 4293)
Technical Assistance: Available through your local authorized independent dealer. For the location of the dealer nearest you, call 1-866-708-9180 or visit			Gloss / Sheen	Flat (0 - 4 @ 85°)
			Surface Temperature at Application	– Min. 50 °F
www.coronadopaint.com		– Max. 90 °F		
			Thin With	Clean Water
			Clean Up Thinner	Warm Soapy Water
			Weight Per Gallon	11.9 lbs.
				– Min. 40 °F
			Storage Temperature	– Max. 95 °F
		Volatile Organic Compounds (VOC)		
			90 Grams/Lit	ter 0.75 Lbs./Gallon
				,

◊ Reported values are for White. Contact dealer for values of other bases or colors.

Surface Preparation

Surfaces to be painted must be clean, dry, and free of dirt, dust, grease, oil, soap, wax, peeling or flaking paint, water soluble materials and mildew. Remove any peeling or flaking paint, and sand these areas to feather edges smooth with adjacent surfaces. Glossy areas should be dulled. Drywall surfaces must be free of sanding dust. Spot prime before and after filling nail holes, cracks, and other surface imperfections.

New plaster or masonry surfaces must be allowed to cure (30 days) before applying base coat. Cured plaster should be hard, have a slight sheen and maximum pH of 10; soft, porous or powdery plaster indicates improper cure.

Primers: New surfaces should be fully primed. Previously painted surfaces should be primed or spot primed as necessary. There are a number of specialty primers available in our family of brands that can be used on difficult substrates such as bleeding woods, hard glossy surfaces, or other substrates where paint adhesion or stain blocking is a problem. Your dealer can recommend the right problem solving primer necessary to meet your needs.

WARNING! If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH-approved respirator to control lead exposure. Carefully clean up with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Application

Stir product thoroughly with a circular, lifting motion ensuring even mixing throughout.

Roller - 3/8" to 1 1/4 " nap, depending on surface texture

Brush – Nylon or polyester filament

Spray, Airless – Fluid Pressure—1,500 to 2,000 PSI; Tip — .019 - .021 Orifice.

Clean Up

Clean up with warm, soapy water.

USE COMPLETELY OR DISPOSE OF PROPERLY. Dry empty containers may be recycled in a can recycling program. Local disposal requirements vary; consult your sanitation department or state-designated environmental agency on disposal options.

Environmental Health & Safety Information WARNING!

Cancer Hazard. Contains Crystalline Silica that can cause cancer when in respirable form (spray mist or sanding dust).

Use only with adequate ventilation. Do not breathe spray mist or sanding dust. Ensure fresh air entry during application and drying. Avoid contact with eyes and prolonged or repeated contact with skin. Avoid exposure to dust and spray mist by wearing a NIOSH approved respirator during application, sanding and clean up. Follow respirator manufacturer's directions for respirator use. Close container after each use. Wash thoroughly after handling.

WARNING Cancer and Reproductive Harm– www.P65warnings.ca.gov

FIRST AID: In case of eye contact, flush immediately with plenty of water for at least 15 minutes; for skin, wash thoroughly with soap and water. If symptoms persist, seek medical attention. If you experience difficulty breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical attention immediately.

IN CASE OF SPILL – Absorb with inert material and dispose of as specified under "CleanUp".

KEEP OUT OF REACH OF CHILDREN PROTECT FROM FREEZING

Refer to Safety Data Sheet for additional health and safety information.