

HP | HIGH PERFORMANCE

HP4100

Fast-Cure Polyamide Epoxy Satin

General Description

HP4100 Fast-Cure Polyamide Epoxy is a unique satin sheen epoxy coating that can be put into service as soon as 24 hours after application and can be applied in temperatures as low as 35 °F (1.7 °C). This high-solids coating exhibits excellent chemical and abrasion resistance and may be used directly on most substrates and as a high durability floor coating. This is a two-component product that requires 1 part of the proper "A" component mixed with 1 part of part "B" catalyst. The components are already premeasured to the proper mix ratio. No measuring required. Do not mix partial kits.

- Low temperature applications
- Multi-surface, impact- Resistant
- Excellent acid and chemical resistance
- High-solids, low-sheen finish

Usage

Resin

Designed for coating properly prepared and/or primed steel, iron, concrete, and non-ferrous metals. For use in standard and low temperature applications in the food and beverage processing industry, industrial maintenance market, industrial flooring, fabrication market, chemical processing market, and transportation market. This product may be used interior or exterior, however if left without top-coating in exterior applications, the coating may prematurely chalk from UV exposure.

Colors	Clear (00), Silver Gray (70),
	Battleship Gray (75), Black (80)
Bases	7B, 8B, 9B
Colorant System	Industrial

Technical Data (Gloss)

Volume Solids (mix	ed)	76 ± 2%		
Spread Rate Per Ga	llon	350 – 500 Sq. Ft.		
Recommended	Wet:	3.2 - 4.6 mils		
Film Thickness	Dry:	2.3 – 3.3 mils		
Depending on surface texture and porosity.				
Dry Time @ 77 °F (25 °C) @ 50% RH	To Touch:	3 – 4 hours		
	To Recoat:	8 hours		
123 C/W 30% NA				

Maximum abrasion and chemical resistance is achieved at full cure, which is generally within 3 – 5 days. Care should be taken to prevent damage to the coating during the curing process. High humidity and cool temperatures will result in longer dry, recoat and cure times.

Return to Service:

Recoat after 72 hours: Abrade the surface to ensure proper inter-coat adhesion.

Surface Temperature **During Application** Max: 100 °F 103 ± 4 KU Viscosity Flash Point 80 °F (TT-P-141, Method 4293) Sheen / Gloss 35 - 40 @ 60° Clean Up HP7040 Thinner Do Not Thin Mixed Ratio (by volume) 1:1 Induction time @ 77 °F (25 °C) 30 minutes Pot Life @ 77 °F (25 °C) 3 hours Weight Per Gallon (mixed) 12.8 lbs. Min: 45 °F Storage Temperature Max: 95 °F VOC (Catalyzed) < 250 g/L

Surface Preparation

Surfaces must be clean, dry and free of all grease, dirt, dust, oil and wax. Clean all surfaces using HP6000 Oil & Grease Emulsifier. Remove all remaining loose paint, rust and mill scale via Hand Tool Cleaning (SSPC-SP 2) or Power Tool cleaning (SSPC-SP 3). Fill holes and cracks and sand smooth. Glossy surfaces must be fully deglossed. Moderate to heavily rusted areas must be thoroughly prepared and active rust should be properly removed.

All masonry surfaces must be allowed to cure a minimum of 30 days before painting. Acid etch or abrasive blast all slick, glazed concrete or concrete with laitance. For acid etching, follow all manufacturer's directions and safety instructions. Rinse thoroughly and allow to dry.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Informational Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Primer Systems

Ferrous Metal:

Polyamide epoxy

24 hours

Prime with HP1550 Concrete and Metal Epoxy Primer or HP1100 Acrylic Metal Primer.

Galvanized, Aluminum and Non-Ferrous Metals:

Prime new or un-rusted metal with HP1100 Acrylic Metal Primer or HP1750 Waterborne Bonding Primer. **Weathered galvanized** should be primed with HP1550 Concrete and Metal Epoxy Primer.

Concrete and Masonry: Prime concrete with one coat of HP1550 Concrete and Metal Epoxy Primer or HP1560 Quick Set Epoxy Floor Sealer.

Previously Painted Surfaces: HP4100 can be applied over most old industrial finishes in good condition. Test patches are recommended to check for wrinkling or lifting of existing coatings. HP1550 Concrete and Metal Epoxy Primer may be used as a barrier coat over all existing coatings.

Compliance & Certifications

FEDERAL	✓	
ОТС	✓	
OTC II	✓	
CARB02	✓	
CARB07	✓	
CARB19	✓	
UTAH	✓	
AZMC	✓	
SCAQMD	×	
MPI	NA	

Suitable for Use in USDA Inspected Facilities

Mixing Instructions

This is a two-component product and is preproportioned for error free mixing. Mix "A" & "B" separately.

- 1.) Carefully empty the entire contents of HP4100 Part B and the contents of HP4100 Part A component resin into a separate metal pail, large enough to hold both Part A and Part B, scraping the sides of both parts to ensure all liquid has been added.
- **2.)** Using a drill mixer at low speed, blend this mixture for three to five minutes until completely blended. Keep the mixing blade turning at a slow speed to minimize whipping air into material. Scrape sides of pail during the mixing process.
- **3.)** Allow to induct for 30 minutes at 77 $^{\circ}$ F (25 $^{\circ}$ C) prior to application.

Pot Life:

3 hours at 77 °F (25 °C) 5 hours at 50 °F (10 °C) 1 hours at 100 °F (37.8 °C)

Limitations

- This product will not cure at surface temperatures below 35 °F (1.7 °C).
- This product will amber and chalk if exposed to sunlight. Where color and gloss retention is important, top-coating will be necessary.

Technical Assistance

Available through your local authorized independent Benjamin Moore retailer.

call 1-866-708-9180

visit www.benjaminmoore.com

Application

Airless Spray (Preferred Method): Tip range between .019 and .021. Total fluid output pressure at tip should not be less than 2100 psi.

Air Spray (Pressure Pot): 704 or 765 air cap and Fluid Tip E.

Brush: Natural Bristle only

Roller: Industrial Cover with Phenolic core. $\frac{1}{4}$ " – $\frac{1}{2}$ " nap.

NOTE: Do not allow material to remain in hoses, gun or spray equipment. Thoroughly flush all equipment with HP7040. Do not thin.

Where non-skid characteristics are desired, hand broadcast an appropriate anti-slip aggregate into the wet film then back-roll to encapsulate. HP6300 works well in opaque finishes although will be noticeable in clear finishes.

All epoxy coatings will chalk and fade if applied on exterior surfaces subjected to direct sunlight. Where color and gloss retention is important, top-coating will be necessary. HP4100 will stain with prolonged exposure to some solvents and chemicals or in kennels if exposed to animal waste. This staining will not affect the durability or protective qualities of the coating. Do not apply if material, substrate or ambient temperature is below 35 °F (1.7 °C). Relative humidity should be below 90%. Do not apply if within 5 degrees of dew point or if rain is expected within 12 hours of application.

CHEMICAL RESISTANCE GUIDE (NON-IMMERSION)		
Fresh Water	Excellent	
Salt Water	Excellent	
Acids	Excellent	
Alkalis	Good	
Solvents	Good	
Fuel	Good	
Acidic Salt Solutions	Excellent	
Alkaline Salt Solutions	Good	
Neutral Salt Solutions	Excellent	

TEST DATA			
Flexibility (ASTM D1737)	Pass ¼" Mandrel		
Sag Resistance (ASTM D4400	Passes 12 mils		
Dry Heat Resistance	200 °F (93 °C)		
Wet Heat Resistance	150 °F (65.5 °C)		
Adhesion (ASTM D3359)	Pass 5B		
Abrasion Resistance (ASTM D4060) CS-17 Wheel, 1000g load	75 mg loss after 1000 cycles		
Humidity (ASTM D4585) (2 coats / 1000 Hours)	Face Corrosion: None		
	Face Blistering: None		
	Rating: 10, Rust: 0.00%		
Salt Spray (ASTM B117) (2 coats / 1000 Hours)	Face Corrosion: None		
	Face Blistering: None		
	Rating: 10, Rust: 0.00%		

Clean Up

Wash brushes, rollers, and other painting tools with HP7040 Epoxy Thinner immediately after use. Do not allow material to remain in hoses, gun or spray equipment. Thoroughly flush all equipment with HP7040.

Environmental Health & Safety Information

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Wash face, hands and any exposed skin thoroughly after handling. Do not eat, drink or smoke when using this product. Use only outdoors or in a well-ventilated area. In case of inadequate ventilation wear respiratory protection. Contaminated work clothing should not be allowed out of the workplace. Wear protective gloves. Do not breathe dust/fume/gas/mist/vapors/spray. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Keep container tightly closed. Ground and bond container and receiving equipment. Use only non-sparking tools. Take action to prevent static discharges.

CAUTION: All floor coatings may become slippery when wet. Where non-skid characteristics are desired, use an appropriate anti-slip aggregate.

IMPORTANT: Designed to be mixed with other components. Mixture will have hazards of all components. Before opening packages, read all warning labels. Follow all precautions.

WARNING Cancer and Reproductive Harm— www.P65Warnings.ca.gov
Refer to the product label & Safety Data Sheet for product specific information.

IN CASE OF SPILL – Absorb with inert material and dispose of as specified under "Clean Up".

FOR PROFESSIONAL USE ONLY KEEP OUT OF REACH OF CHILDREN

Refer to Safety Data Sheet for additional health and safety information.