



SILICONE ALKYD HI HEAT COATING V264

Features

- Aluminum color
- High-heat resistance allows for use on industrial machinery, hot metal ducting and exhaust vents
- Fast dry; quick return to service
- Uses include heat stacks, boiler jackets, heat exchangers, drying kilns, and incinerators
- Not for interior residential use

Recommended For

Ferrous Metal (Steel & Iron) Corotech® Silicone Alkyd Hi Heat Coating can be used on high heat stacks, boiler jackets or breechings, heat exchangers, drying kilns, incinerators and oven exteriors. Do not apply to galvanized metal.

General Description

Silicone Alkyd High-Heat Coating is designed to protect steel that is exposed to heat ranges up to 800 °F (425 °C). This product exhibits excellent weathering, resists mild industrial chemicals and moisture and is specific to industrial use.

Limitations

- Not intended for residential or commercial use.
- Not for immersion or extreme chemical exposure service.
- Do not apply to galvanized metal.
- Surface and air temperatures for application must be between 50 °F and 100 °F.
- The surface must be dry and at least 5 degrees above the dew point. Humidity must be 90% or less.

Product Information

Colors — Standard: Aluminum (78)	Technical Data \diamond Aluminum																		
— Tint Bases: N/A	Vehicle Type Modified Silicone Alkyd																		
— Special Colors: Contact your retailer.	Pigment Type Aluminum Metal																		
Certification & Qualifications: The product supported by this data sheet contains a maximum of 500 grams per liter VOC / VOS (4.17 lbs. /gal.) excluding water & exempt solvents. Masters Painters Institute MPI # 2 Meets the performance requirements of TT-P-28H	Volume Solids 43 ± 1.0%																		
	Coverage per Gallon at Recommended Film Thickness 350 – 400 Sq. Ft.																		
Technical Assistance Available through your local authorized independent Benjamin Moore retailer. For the location of the retailer nearest you, call 1-866-708-9180 or visit www.benjaminmoore.com	<table border="0" style="width:100%"> <tr> <td style="width:60%">Recommended Film Thickness</td> <td style="width:20%">– Wet</td> <td style="width:20%">4.0 - 4.6 mils</td> </tr> <tr> <td></td> <td>– Dry</td> <td>1.7 - 2.0 mils</td> </tr> </table>	Recommended Film Thickness	– Wet	4.0 - 4.6 mils		– Dry	1.7 - 2.0 mils												
	Recommended Film Thickness	– Wet	4.0 - 4.6 mils																
	– Dry	1.7 - 2.0 mils																	
<table border="1" style="width:100%"> <thead> <tr> <th>VOC REGION</th> <th>COMPLIANT</th> </tr> </thead> <tbody> <tr><td>FEDERAL</td><td>YES</td></tr> <tr><td>OTC</td><td>YES</td></tr> <tr><td>OTCII</td><td>YES</td></tr> <tr><td>CARB</td><td>YES</td></tr> <tr><td>CARB07</td><td>NO</td></tr> <tr><td>UTAH</td><td>YES</td></tr> <tr><td>AZMC</td><td>YES</td></tr> <tr><td>SCAQMD</td><td>NO</td></tr> </tbody> </table>	VOC REGION	COMPLIANT	FEDERAL	YES	OTC	YES	OTCII	YES	CARB	YES	CARB07	NO	UTAH	YES	AZMC	YES	SCAQMD	NO	Depending on surface texture and porosity. Be sure to estimate the right amount of paint for the job. This will ensure color uniformity and minimize the disposal of excess paint.
VOC REGION	COMPLIANT																		
FEDERAL	YES																		
OTC	YES																		
OTCII	YES																		
CARB	YES																		
CARB07	NO																		
UTAH	YES																		
AZMC	YES																		
SCAQMD	NO																		
	<table border="0" style="width:100%"> <tr> <td style="width:60%">Dry Time @ 77 °F (25 °C) @ 50% RH</td> <td style="width:20%">– Tack Free</td> <td style="width:20%">1 Hour</td> </tr> <tr> <td></td> <td>– To Recoat*</td> <td>4 Hours</td> </tr> <tr> <td></td> <td>– Full Cure</td> <td>7 Days Air Dry</td> </tr> </table>	Dry Time @ 77 °F (25 °C) @ 50% RH	– Tack Free	1 Hour		– To Recoat*	4 Hours		– Full Cure	7 Days Air Dry									
	Dry Time @ 77 °F (25 °C) @ 50% RH	– Tack Free	1 Hour																
	– To Recoat*	4 Hours																	
	– Full Cure	7 Days Air Dry																	
	*Maximum Recoat: Unlimited																		
	High humidity and cool temperatures will result in longer dry, recoat and service times.																		
	Dries By Oxidation																		
	Viscosity 75 – 85 KU																		
	Flash Point 104 °F (TT-P-141, Method 4293)																		
	Gloss / Sheen N/A																		
	<table border="0" style="width:100%"> <tr> <td style="width:60%">Surface Temperature at Application</td> <td style="width:20%">– Min.</td> <td style="width:20%">50 °F</td> </tr> <tr> <td></td> <td>– Max.</td> <td>100 °F</td> </tr> </table>	Surface Temperature at Application	– Min.	50 °F		– Max.	100 °F												
	Surface Temperature at Application	– Min.	50 °F																
	– Max.	100 °F																	
	Thin With Do Not Thin																		
	Clean Up Thinner Corotech® V703 Xylene																		
	Weight Per Gallon 9.0 lbs.																		
	<table border="0" style="width:100%"> <tr> <td style="width:60%">Storage Temperature</td> <td style="width:20%">– Min.</td> <td style="width:20%">45 °F</td> </tr> <tr> <td></td> <td>– Max.</td> <td>95 °F</td> </tr> </table>	Storage Temperature	– Min.	45 °F		– Max.	95 °F												
Storage Temperature	– Min.	45 °F																	
	– Max.	95 °F																	
	Volatile Organic Compounds (VOC) 430 Grams/Liter 3.58 Lbs./Gallon																		

\diamond Reported values are for Aluminum.

Surface Preparation

The performance of this product is directly dependent upon the degree of surface preparation employed. All dirt, oils and accumulated salts must be removed prior to employing specific surface preparation methods. SSPC-SP 1 Solvent Cleaning will best accomplish this task.

Previously Painted or Primed Surfaces: Ensure that the surface is clean, dry and free of oil, grease, dirt, salts and any other contaminants. Clean with Corotech V600 Oil & Grease Emulsifier. All blistered and loose paint must be removed. All bare metal must be primed with an initial coat of V264-78 before applying a full coat on the entire surface. Glossy surfaces should be roughened up before painting.

Ferrous Metal: All contaminants, rust and mill scale should be removed prior to application of this product. This is best accomplished by abrasive blasting. A minimum of SSPC-SP 6 Commercial Blast is recommended for severe environmental exposures. Small areas may be cleaned in accordance with SSPC-SP 2 Hand Tool Cleaning or SSPC-SP 3 Power Tool Cleaning or SSPC-SP 11 Power Tool Cleaning to Bare Metal.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Informational Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Application

Mix the product thoroughly before application. The use of a drill mixer at low speed will best accomplish this. Due to the fast dry of this product, only small areas should be coated by brush or roller. Spray application is preferred. Surface and air temperatures for application must be between 50°F and 90°F. The surface must be dry and at least 5 degrees above the dew point. Humidity must be 90% or less.

Airless Spray: Tip range between .013 and .017. Total fluid output pressure at the tip should not be less than 2200 PSI. Preferred pressure is 2500 PSI.

Air Spray: [Pressure Pot] DeVilbiss 510 gun, with 704 air cap and fluid tip FF. Pot pressure should be at 40 - 60 and atomizing pressure should be 15 - 25.

Brush or Roll: Can be brushed using a natural bristle brush or rolled using a 3/8" - 1/2" lambs wool phenolic core roller cover.

NOTE: Do not allow material to remain in hoses, gun, or spray equipment. Thoroughly flush all equipment with recommended thinner. No reduction is necessary.

Clean Up

Clean with Corotech® V703 Xylene.

Environmental Health & Safety Information

DANGER!

Causes skin irritation

May cause an allergic skin reaction

May cause genetic defects

May cause cancer

Causes damage to organs through prolonged or repeated exposure

May be fatal if swallowed and enters airways

Flammable liquid and vapor

Prevention: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Wash face, hands and any exposed skin thoroughly after handling. Contaminated work clothing should not be allowed out of the workplace. Wear protective gloves. Do not breathe dust /fume /mist /vapors /spray. Do not eat, drink or smoke when using this product. Keep away from heat /sparks /open flames /hot surfaces, no smoking. Keep container tightly closed. Ground /bond container and receiving equipment. Use explosion-proof electrical /ventilating /lighting /equipment. Use only non-sparking tools. Take precautionary measures against static discharge.

Response: If exposed or concerned get medical attention. If skin irritation or rash occurs get medical attention. If on skin (or hair) take off immediately all contaminated clothing. Rinse skin with water. Wash contaminated clothing before reuse. If swallowed immediately call a POISON CENTER or physician. Do NOT induce vomiting. In case of fire use CO₂, dry chemical, or foam for extinction..

Storage: Store locked up. Store in a well-ventilated place. Keep cool.

Disposal: Dispose of contents /container to an approved waste disposal plant.

DANGER - Rags, steel wool or waste soaked with this product may spontaneously catch fire if improperly discarded. Immediately after use, place rags, steel wool or waste in a sealed water-filled metal container.



WARNING Cancer and Reproductive Harm—
www.P65warnings.ca.gov

This document represents hazards of the product referenced above. Refer to the individual Safety Data Sheet for hazards of the specific product you will be using.

KEEP OUT OF REACH OF CHILDREN

**Refer to Safety Data Sheet for
additional health and safety information.**