

Features

- Tint Base For Custom Colors
- Ready To Use
 Formulation
- Uniform Penetration
- Superior Grain Definition
- Resists Fading and Bleeding
- Fast Drying For Lacquers

Recommended For

Kitchen Cabinets, Wood Floors, Furniture, Window & Door Trim, Baseboards & Molding, Interior Doors & Hand Rails.

QUICKSTAIN[®] ALKYD WIPING STAIN 1U.1000

General Description

Lenmar[®] QuickStain[®] Alkyd Wiping Stains have been uniquely designed for the professional woodworker in the Flooring, Furniture & Cabinet Industry and are formulated for ease of use, and color stability. The major benefits of this stain include: a natural / clear tint base for custom tinting with industrial colorants, ease of application for uniform penetration, superior grain definition, and resistance to bleeding and fading.

Limitations

For floor applications, wait 2-3 hours before proceeding with topcoats.

Product Information			
Colors — Standard:	Technical Data◊	Nat	ural/Clear Base
N/A	Vehicle Type		Alkyd
	Pigment Type		N/A
— Tint Bases: Weight Solids Volume Solids	Weight Solids		10.3%
	Volume Solids		8.9%
Can be tinted with Industrial Colorants	Coverage per Gallon at 1 mil DFT N/		N/A
	Recommended Film Thickness	- Wet	N/A
— Special Colors:		– Dry	N/A
(1	Dry Time @ 75 °F (23.8 °C) @ 50% RH	– Tack Free	15 Minutes
		– To Recoat	30 Minutes
Certification & Qualifications: VOC compliant in federally regulated areas only	High humidity and cool temperatures will result in longer dry, recoat and service times.		
	Dries By		Oxidation
The products supported by this data sheet contain a maximum of 750 grams per liter VOC /VOS (6.26 lbs/gal.) excluding water & exempt solvents.	Viscosity	18 – 22 Seconds (#2 Zahn)	
	Flash Point	100 °F (37.8 °C)	
	Gloss / Sheen		N/A
	Surface Temperature at Application	– Min.	68 °F
		– Max.	90 °F
	Thin With		Do Not Thin
	Clean Up Thinner	17	A.137 Mineral Spirits
	Weight Per Gallon		7.33 lbs
Technical Assistance: Available through your local authorized independent Lenmar dealer. For the location of the dealer nearest you, call 1-866-708-9180 or visit www.lenmar-coatings.com	Storage Temperature	– Min.	50 °F
		– Max.	90 °F
	Volatile Organic Compounds (VOC)		
	736 Grams/Liter 6.14 Lbs./Gallon		

QuickStain Alkyd Wiping Stain 1U.1000

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Informational Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Application

Over properly prepared interior wood surfaces, apply only one full coat of QuickStain[®] Alkyd Wiping Stain by spray, natural bristle brush or with a clean lint-free cloth. Remove all excess stain within 5 minutes after application. When dry (usually 30 minutes), continue with sealer and topcoat system in accordance with their Product Data Sheets. Check adhesion before proceeding with this type of application. See characteristics for finish options and recommended dry times. For floor applications, wait 2-3 hours before proceeding with topcoats.

Specifications

Moisture content of wood should be no higher than 9%. Wood must be free of all surface contaminants. Using 120 – 150 grit sandpaper, sand with the grain and remove all dust. Thoroughly mix stain and intermix multiple containers of same color. Test color before proceeding. Color intensity may vary due to wood species, surface preparation, and method of application. Submerse stain soaked rags in water to avoid spontaneous combustion. Read label and SDS for additional information and warnings

Clean up

Clean up with 1A.137 Mineral Spirits.

Environmental Health & Safety Information DANGER!

Causes skin irritation

Suspected of causing cancer

May cause drowsiness or dizziness

Causes damage to organs through prolonged or repeated exposure

May be fatal if swallowed and enters airways

Flammable liquid and vapor

Prevention: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Wash face, hands and any exposed skin thoroughly after handling. Do not breathe dust/fume/gas/mist/vapors/spray. Do not eat, drink or smoke when using this product. Use only outdoors or in a well-ventilated area. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosionproof electrical/ventilating/lighting/equipment. Use only nonsparking tools. Take precautionary measures against static discharge. Keep cool.

Response: IF exposed or concerned: Get medical advice/attention. If skin irritation occurs: Get medical advice/attention. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing. IF SWALLOWED: Immediately call a POISON CENTER or doctor/physician. Do NOT induce vomiting. In case of fire: Use CO2, dry chemical, or foam for extinction.

Storage: Store locked up. Store in a well-ventilated place. Keep container tightly closed.

Disposal: Dispose of contents/container to an approved waste disposal plant.

DANGER - Rags, steel wool or waste soaked with this product may spontaneously catch fire if improperly discarded. Immediately after use, place rags, steel wool or waste in a sealed water-filled metal container.

WARNING Cancer and Reproductive Harmwww.P65warnings.ca.gov

KEEP OUT OF REACH OF CHILDREN

THIS PRODUCT IS INTENDED FOR SHOP OR OEM APPLICATION ONLY.

READ ALL DIRECTIONS BEFORE USE. UNDERSTAND <u>ALL</u> DANGERS WITH THIS PRODUCT PRIOR TO USE.

Refer to Safety Data Sheet for additional health and safety information.