

Features

- Fast 30 minute dry recoat in 4 hours
- Can be top coated with strong, solvent-based coatings
- Tie coat over many existing coatings
- Corrosion protection on all ferrous metals

Recommended For

Ferrous Metal such as Steel & Iron. Corotech® Prep All Universal Metal Primer is a high performance coating specifically designed for application directly to ferrous metal substrates. It provides corrosion resistance for both interior and exterior steel surface in mildly corrosive conditions.

PREP ALL UNIVERSAL METAL PRIMER V132

General Description

Prep All Universal Metal Primer is an economical, single-component primer engineered to provide corrosion protection on all ferrous metals. This quick-drying formula provides fast production times, and its alkyd resin formulation allows for application on a wide variety of intermediate and finish coat products. Formulated for an airless spray application, it can also be applied by HVLP spray, brushes, or rollers.

Limitations

- Not recommended for non-ferrous metals such as galvanized, aluminum or for use in immersion service
- Do not apply if material, substrate or ambient temperature is below 50 °F (10 °C)
- Relative humidity should be below 90%. Do not apply if within 5 degrees of dew point or if rain is expected within 12 hours of application

	Pro	duct Informat	tion			
Colors — Standard:			Technical Data◊	White		
White (01), Red (20), Gray (70)			Vehicle Type	Phenolic Alkyd		
			Pigment Type	Titanium Dioxide		
Can be tinted with up to 2.0 fl. oz. of IM colorants per gallon.			Volume Solids	50 ± 1.0%		
— Tint Bases:			Coverage per Gallon at Recommended Film Thick			
			Recommended Film Thickness	– Wet	3.6 – 4.6 mils	
— Special Colors:				– Dry	1.8 - 2.3 mils	
Contact your retailer.			Depending on surface texture and porosity.			
Certification & Qualifications :			Dry Time @ 77 °F (25 °C) @ 50% RH	– Tack Free– To Recoat	30 Minutes 4 Hours	
The products supported by this data sheet contain a maximum of 400 grams per liter VOC / VOS (3.33 lbs. /gal.) excluding water & exempt solvents. Suitable For Use In USDA Inspected Facilities	VOC REGION	COMPLIANT		– Full Cure	7 Days	
	FEDERAL	YES		High humidity and cool temperatures will result in longer dry, recoat and service times.		
	ОТС	YES	-, -			
	OTCII	NO	,		Oxidation	
	CARB	YES	Viscosity	70 – 75 KU		
Meets Federal Specifications TT-P-664	CARB07	NO	Flash Point	50 °F (TT-P-141, Method 4293) 0 – 3 @ 60°		
Master Painters Institute MPI # 76	UTAH	NO	Gloss/Sheen			
	AZMC	YES	Surface Temperature at Application	– Min.	50 °F	
	SCAQMD	NO		– Max.	90 °F	
Technical Assistance:	Thin With	Not Recommended				
Available through your local authorized independent Benjamin Moore retailer. For the location of the retailer nearest you, call 1-866-708-9180 or visit www.benjaminmoore.com			Clean Up Thinner	Corotech® V703 or Xylene		
			Weight Per Gallon		11.2 lbs.	
			Storage Temperature	– Min. – Max.	40 °F 95 °F	
			Volatile Orgar 393 Grams/Lit	nic Compounds (er 3.28 Lbs./G	•	

 $[\]Diamond$ Reported values are for White. Contact retailer for values of other bases or colors

Surface Preparation

All surfaces must be sound, dry, clean and free of oil, grease, dirt, mildew, mill scale, form release agents, curing compounds, loose and flaking paint and other surface contaminants.

NEW SURFACES: Steel: For best results, abrasive blast to a commercial blast (SSPC-SP 6). For mild conditions, a hand or power tool cleaning (SSPC-SP 2) may be satisfactory, but performance is dependent upon the degree of surface preparation.

Previously Painted Surfaces: Wash and rinse any areas that may have oil or grease residue. Dull glossy surfaces by lightly sanding. Remove sanding dust. Remove loose paint. All areas that are rusting, blistering, cracking or peeling must be cleaned to bare metal. If more than 25% of the surface is involved, sandblast the entire surface to a commercial blast and prime. If less than 25% of the surface is involved, clean soiled areas and spot prime.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Informational Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Application

Mix the product thoroughly before application. The use of a drill mixer at low speed will best accomplish this.

Airless Spray: Tip range between .013 and .017. Total fluid output pressure at tip should not be less than 2200 psi.

Air Spray (Pressure Pot): DeVilbis MBC or JGA gun, with 704 or 765 air cap and Fluid Tip E.

Can be brushed using a natural bristle brush or rolled using a 3/8" lambs wool or 1/4" - 1/2" synthetic roller cover. Roll in one direction, rewet, then cross roll.

NOTE: Do not allow material to remain in hoses, gun or spray equipment. Thoroughly flush all equipment with recommended thinner. No reduction is necessary. Do not apply if material, substrate or ambient temperature is below 50° F (10° C). Relative humidity should be below 90%. Do not apply if within 5 degrees of dew point or if rain is expected within 12 hours of application.

TES	T DATA	CHEMICAL RESISTANCE GUIDE (NON-IMMERSION)			
Steam Resistant	Yes	Fresh Water			
Flexibility (ASTM D1737)	Pass ¼" Mandrel	Salt Water			
Dry Heat Resistance	250° F	Acids			
Wet Heat Resistance	150° F	Alkalis	See Finish		
Adhesion (ASTM D3359)	Pass 5B	Solvents	Coat Data Sheets for		
Salt Spray		Fuel	Resistance Information.		
(ASTM B117) (1.8 mils w/2.5 mils V-500; 1000 Hours)	Face Corrosion- None Face Blistering-None	Acidic Salt Solutions			
Humidity (ASTM D4585 w/V-500 Topcoat (1000 Hours)	Face Corrosion- None Face Blistering-None	Alkaline Salt Solutions Neutral Salt Solutions			
SYSTEMS RECOMMENDATIONS					
COMPATIBLE FINISHES					

V200 Line, V201 Line, V220 Line, V230 Line, V231 Line, V300 Line, V330 Line, V400 Line, V410, V440 Line, V500, V510, V515, V520 and Other Acrylics & Alkyds

COMPATIBLE INTERMEDIATES

V160 Line

Clean Up

Clean with Corotech® V703 or Xylene

Environmental Health & Safety Information DANGER!

Causes skin irritation

Causes serious eye irritation

May cause an allergic skin reaction

May cause cancer

Causes damage to organs through prolonged or repeated exposure

May be fatal if swallowed and enters airways Highly flammable liquid and vapor

Prevention: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Wash face, hands and any exposed skin thoroughly after handling. Contaminated work clothing should not be allowed out of the workplace. Do not breathe dust/fume/mist/vapors/spray. Do not eat, drink or smoke when using this product. Keep away from heat/sparks/open flames/hot surfaces, no smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosionproof electrical/ventilating/lighting/equipment. Use only nonsparking tools. Take precautionary measures against static Wear protective discharge. gloves/protective clothing/eye protection/face protection.

Response: If exposed or concerned get medical attention. If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists get medical attention. If skin irritation or rash occurs get medical attention. If on skin (or hair) take off immediately all contaminated clothing. Rinse skin with water. Wash contaminated clothing before reuse. If swallowed immediately call a POISON CENTER or physician. Do NOT induce vomiting. In case of fire use CO2, dry chemical, or foam for extinction.

Storage: Store locked up. Store in a well-ventilated place. Keep

Disposal: Dispose of contents/container to an approved waste disposal plant.

DANGER - Rags, steel wool or waste soaked with this product may spontaneously catch fire if improperly discarded. Immediately after use, place rags, steel wool or waste in a sealed water-filled metal container.



This document represents hazards of the product referenced above. Refer to the individual Safety Data Sheet for hazards of the specific product you will be using.

FOR METAL SUBSTRATES ONLY **KEEP OUT OF REACH OF CHILDREN** FOR PROFESSIONAL USE ONLY

Refer to Safety Data Sheet for additional health and safety information.