Benjamin Moore



Features

- Fast 30 minute dry
- No orange peel
- Airless or HVLP systems
- For all ferrous metal surfaces
- Hard scratch- and impact-resistant coating

Recommended For

Properly Prepared and Primed Ferrous & Non-Ferrous Metal.

QUICK DRY ALKYD ENAMEL SEMI-GLOSS CV231

General Description

Quick Dry Alkyd Enamel is a high-performance, singlecomponent, quick-dry, rust preventive enamel formulated for use on ferrous metal substrates. It provides corrosion resistance for both interior and exterior steel surfaces. Not recommended for non-ferrous metals such as galvanized, aluminum unless properly primed, Quick Dry Alkyd Enamel may be applied to new or properly prepared, rusted surfaces.

Limitations

- Not recommended for non-ferrous metals such as galvanized, aluminum unless properly primed.
- Not recommended for floors or for extreme environments.
- Not recommended for exterior wood surfaces.
- Not recommended for immersion service or contact with strong solvents.

Colors — Standard: White (01), Black (80), Wrought Iron Black (81) – <i>Flat Finish</i>			Technical Data◊	White
			Vehicle Type	Vinyl Toluene Alkyc
			Pigment Type	Titanium Dioxide
— Tint Bases:			Volume Solids	63 ± 1.0%
N/A			Coverage per Gallon at Recommended Film Thio	xness 350 – 450 Sq. Ft
— Special Colors: Contact your retailer. Certification & Qualifications:			Recommended Film Thickness	– Wet 3.0 – 3.8 mils
				– Dry 1.9 – 2.4 mils
			Depending on surface texture and porosity. Be sure to estimate the right amount of paint for the job. This wi ensure color uniformity and minimize the disposal of exces	
Certification & Quantications:			paint.	
The products supported by this data sheet contain a maximum of 250 grams per liter VOC / VOS (2.08 lbs. /gal.) excluding water & exempt solvents. Suitable for use in USDA inspected facilities	VOC REGION	COMPLIANT	Dry Time @ 77 °F	 – Tack Free 30 Minutes – To Recoat * 2 Hours
	FEDERAL	YES	(25 °C) @ 50% RH	– To Recoat * 2 Hours – Full Cure 5 – 7 Days
	отс	YES	*Maximum Basastu Soo	
	OTCII	YES	Recoat Information	*Maximum Recoat: See Application Section For Importan Recoat Information
	CARB	YES		High humidity and cool temperatures will result in longer dry
	CARB07	YES	recoat and service times.	
	UTAH	YES	Dries By	Oxidatior
	AZMC	YES	Viscosity	75 – 80 KL
	SCAQMD	NO	Flash Point	50 °F (TT-P-141, Method 4293
Technical Assistance	nondont Roniami	Mooro rotailor	Gloss/Sheen Wrou	Semi-Gloss (30-50 @ 60°) ight Iron Black - Flat (0-5 @ 60°)
Available through your local authorized independent Benjamin Moore retailer. For the location of the retailer nearest you, call 1-866-708-9180 or visit www.benjaminmoore.com			Surface Temperature at Application	<u>– Min. 50 °F</u> – Max. 100 °F
			Thin With	Do Not Thir
			Clean Up Thinner Mir	neral Spirits or High Flash Naphtha
			Weight Per Gallon	12.6 lbs
			Storage Temperature	<u>– Min. 45 °F</u> – Max. 95 °F
			Volatile Organ	ic Compounds (VOC)

◊ Reported values are for White. Contact retailer for values of other bases or colors.

Surface Preparation

All surfaces must be sound, dry, clean and free of oil, grease, dirt, mildew, mill scale, form release agents, curing compounds, loose and flaking paint and other surface contaminants.

NEW SURFACES: Steel: For best results, abrasive blast to a commercial blast (SSPC-SP 6). For mild conditions, a hand or power tool cleaning (SSPC-SP 2) may be satisfactory, but performance is dependent upon the degree of surface preparation. For additional protection, the use of a rust inhibitive primer such as V133 Shop Cote Metal Primer or V131/V132 Universal Primer is recommended.

Previously Painted Surfaces: Wash and rinse any areas that may have oil or grease residue using Corotech V630 Oil & Grease Emulsifier. Dull glossy surfaces by lightly sanding. Remove sanding dust. Remove loose paint. All areas that are rusting, blistering, cracking or peeling must be cleaned to bare metal. If more than 25% of the surface is involved, sandblast the entire surface to a commercial blast and prime. If less than 25% of the surface is involved, clean soiled areas and spot prime.

Galvanized Metal or Aluminum: Apply 1 coat of V110 Acrylic Metal Primer or V175 Waterborne Bonding Primer.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Application

Mix the product thoroughly before application. The use of a drill mixer at low speed will best accomplish this. Spray application only.

Airless Spray: Tip range between .013 and .017. Total fluid output pressure at tip should not be less than 2200 psi.

Air Spray (Pressure Pot): DeVilbis MBC or JGA gun, with 704 or 765 air cap and Fluid Tip E.

If necessary, small areas can be brushed or rolled using a Natural Brush or a 3/8" lambs wool or 1/4" - 1/2" synthetic roller cover. Roll in one direction, rewet, then cross roll.

NOTE: Do not allow material to remain in hoses, gun or spray equipment. Thoroughly flush all equipment with recommended thinner. No reduction is necessary. Do not apply if material, substrate or ambient temperature is below 50°F (10 °C). Relative humidity should be below 90%. Do not apply if within 5 degrees of dew point or if rain is expected within 12 hours of application.

Maximum Recoat: 18 hrs. (Light sanding required after 18 hrs.) Full Cure: 5-7 Days

TEST DATA		
Fungal Resistance (TT-P-18)	No Mildew	
Flexibility (ASTM D1737)	Pass ¼" Mandrel	
Dry Heat Resistance	200 °F	
Wet Heat Resistance	150 °F	
Adhesion (ASTM D3359)	Pass 5B	
Salt Fog Resistance (ASTM B117) Two coats over V132 Primer	200 Hours-Pass (Rating: 10, Rust Area: 0.00%)	

CHEMICAL RESISTANCE GUIDE (NON-IMMERSION)			
Fresh Water	Excellent		
2% Sodium Hydroxide	Excellent		
5% Acetic Acid	Excellent		
Lactic Acid	Excellent		
Mineral Oil	Excellent		

SYSTEMS RECOMMENDATIONS

COMPATIBLE PRIMERS

V110 Line, V114, V130 Line, CV131 Line, CV132 Line, CV133 Line, V140 Line, CV142 Line, V155 Line, CV150 Line, V160 Line, V163, V175, V180 and Other Acrylic and Alkyd Primers

Clean Up

Clean with Mineral Spirits or High Flash Naphtha.

Environmental Health & Safety Information DANGER!

Causes serious eye irritation

May cause an allergic skin reaction

Suspected of causing cancer

May damage fertility or the unborn child

May cause damage to organs through prolonged or repeated exposure

Flammable liquid and vapor

Prevention: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Wash face, hands and any exposed skin thoroughly after handling. Contaminated work clothing should not be allowed out of the workplace. Do not breathe dust/fume/gas/mist/vapors/spray. Keep away from heat, hot surfaces, sparks, open flames and other ignition sources. No smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof electrical/ ventilating/ lighting/ equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Wear protective gloves/protective clothing/eye protection/face protection.

Response: IF exposed or concerned: Get medical advice/attention. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical advice/attention. If skin irritation or rash occurs: Get medical advice/attention. Wash contaminated clothing before reuse. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. In case of fire: Use CO2, dry chemical, or foam for extinction.

Storage: Store locked up. Store in a well-ventilated place. Keep cool.

Disposal: Dispose of contents/container to an approved waste disposal plant.

WARNING: Cancer and Reproductive Harmwww.P65warnings.ca.gov

This document represents hazards of the product referenced above. Refer to the individual Safety Data Sheet for hazards of the specific product you will be using

KEEP OUT OF REACH OF CHILDREN FOR METAL SUBSTRATES ONLY

Refer to Safety Data Sheet for additional health and safety information.

Benjamin Moore & Co., 101 Paragon Drive, Montvale, NJ 07645 Tel: 866-708-9180 Fax: 888-248-2143 <u>www.benjaminmoore.com</u> M72 CV231 EN 042821 ©2017, 2021 Benjamin Moore & Co. Benjamin Moore and the triangle "M" symbol are registered trademarks licensed to Benjamin Moore & Co. All other marks are the property of their respective owner. All rights reserved