

Recommended for exterior use on masonry surfaces such as

stucco, cement and cinder block, as well as on unglazed brick, hardboard, vinyl and aluminum siding, wood, and shakes.

Features

- Excellent flow and leveling. Easy to apply by brush, roller or spray
- Durable finish resists fading, cracking, peeling, blistering, dirt pick-up, alkali, and fumes
- Superior adhesion and excellent resistance to chalking
- Lifetime warranty
- Soap and water clean up
- Mildew resistant
- Low temperature application
- Self priming

REGAL[®] SELECT EXTERIOR PAINT – MOORLIFE[®] FLAT FINISH W105

General Description

A premium quality, self priming, 100% acrylic exterior latex house paint in a popular flat finish. Our latest technological improvement, using 100% acrylic resin and proprietary alkyd technology, provides superior adhesion, especially to chalky substrates. This high solids formula delivers excellent durability, long lasting protection, and is suitable for a variety of exterior surfaces and can be applied at a wider temperature range.

Limitations

 Do not apply when air and surface temperatures are below 35 °F.

stimate the right amour nsure color uniformity xcess paint. ry Time @ 77 °F 25 °C) @ 50% RH	- Wet 4.6 mils - Dry 1.9 mils exture and porosity. Be sure to nt of paint for the job. This will and minimize the disposal of - To Touch 2 Hours - To Recoat 4 Hours temperatures will result in longer
olume Solids overage per Gallon at lecommended Film Thick tecommended Film hickness repending on surface te stimate the right amour nsure color uniformity xcess paint. Try Time @ 77 °F 25 °C) @ 50% RH ligh humidity and cool te ry, recoat and service tin	42% kness 300 – 400 Sq. Ft. - Wet 4.6 mils - Dry 1.9 mils exture and porosity. Be sure to nt of paint for the job. This will and minimize the disposal of - To Touch 2 Hours - To Recoat 4 Hours temperatures will result in longer
coverage per Gallon at tecommended Film Thick tecommended Film Thick tecommended Film hickness repending on surface te stimate the right amour nsure color uniformity xcess paint. Try Time @ 77 °F 25 °C) @ 50% RH ligh humidity and cool te ry, recoat and service tin	Amess 300 – 400 Sq. Ft. - Wet 4.6 mils - Dry 1.9 mils exture and porosity. Be sure to nt of paint for the job. This will and minimize the disposal of - To Touch 2 Hours - To Recoat 4 Hours temperatures will result in longer mes.
Lecommended Film Thick lecommended Film hickness lepending on surface te stimate the right amour nsure color uniformity xcess paint. Try Time @ 77 °F 25 °C) @ 50% RH ligh humidity and cool te ry, recoat and service tin	<u>- Wet 4.6 mils</u> <u>- Dry 1.9 mils</u> exture and porosity. Be sure to nt of paint for the job. This wil and minimize the disposal o <u>- To Touch 2 Hours</u> <u>- To Recoat 4 Hours</u> temperatures will result in longer mes.
hickness lepending on surface te stimate the right amour nsure color uniformity xcess paint. Pry Time @ 77 °F 25 °C) @ 50% RH ligh humidity and cool te ry, recoat and service tin	 Dry 1.9 mils exture and porosity. Be sure to nt of paint for the job. This will and minimize the disposal of <u>- To Touch 2 Hours</u> <u>- To Recoat 4 Hours</u> temperatures will result in longer mes.
stimate the right amour nsure color uniformity xcess paint. Pry Time @ 77 °F 25 °C) @ 50% RH ligh humidity and cool to ry, recoat and service tin	nt of paint for the job. This will and minimize the disposal of <u>- To Touch 2 Hours</u> - To Recoat 4 Hours temperatures will result in longer mes.
25 °C) @ 50% RH ligh humidity and cool to ry, recoat and service tin	- To Recoat 4 Hours temperatures will result in longer mes.
ry, recoat and service tin	mes.
ries By	Evaporation Coalescence
	Eraporation, obalocoonide
iscosity	97 ± 2 KU
lash Point	None
iloss / Sheen	Flat (1 – 5 @ 85°)
Surface Temperature	– Min. 35 °F
t Application	– Max. 100 °F
hin With	See Char
lean Up Thinner	Clean Water
/eight Per Gallon	12.0 lbs
torage Temperature	– Min. 40 °F
lenge remperature	– Max. 90 °F
Volatile Organ	ic Compounds (VOC)
1 1 1	urface Temperature Application hin With lean Up Thinner /eight Per Gallon torage Temperature

Recommended For

Surface Preparation

Surfaces must be clean and free of grease, wax, and mildew. Remove excessive chalk and loose or scaling paint. If previously coated with cementbase water paints, clean by sandblasting. Glossy surfaces must be dulled. Un-weathered areas such as eaves, ceilings, and overhangs should be washed with a detergent solution and/or rinsed with a strong stream of water from a garden hose to remove contaminants that can interfere with proper adhesion. Stains from mildew must be removed by cleaning with Benjamin Moore® Clean (N318) prior to coating the surface. Caution: Refer to the (N318) Clean technical data and material safety data sheets for instructions on its proper use and handling. For metal surfaces, remove rust. Wipe down with paint thinner to remove surface oils if compliant with local requirements.

All new masonry surfaces must be power washed or brushed thoroughly with stiff fiber bristles to remove loose particles. New masonry substrates must be allowed to cure for 30 days before priming or painting. Poured or pre-cast concrete with a very smooth surface should be etched or abraded to promote adhesion, after removing all form release agents and curing compounds.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Informational Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead

Primer/Finish Systems

Regal® Select Exterior is self priming on most properly prepared substrates, including: wood, fiber cement board, hardboard, nonferrous metals and cured masonry surfaces. On bare substrates two coats are required; previously painted surfaces can be finished with 1 or 2 coats. Special Note: Certain custom colors require a Deep Color Base Primer tinted to a special prescription formula to achieve the desired color. Consult your retailer.

Wood and Engineered Wood Products:

Primer: No primer needed

Finish: 2 coats Regal[®] Select Exterior Paint – MoorLife[®] Flat Finish (W105) Bleeding Type Woods, (Redwood and Cedar):

Primer: Fresh Start® Exterior Wood Primer (094); for light tannin bleed situations 1 or 2 coats of Fresh Start® High-Hiding All Purpose Primer (046) may be used.

Finish: 1 or 2 coats Regal® Select Exterior Paint - MoorLife® Flat Finish (W105) Vinyl & Vinyl Composite Siding:

In most cases, a primer is not necessary. Only areas of pitted and porous vinyl siding must be primed. In these cases, we recommend Fresh Start® High-Hiding All Purpose Primer (046), or Fresh Start® Multi-Purpose Latex Primer (N023)

Colors that are safe for use on vinyl siding - Do not paint vinyl with any color darker than the original color or having a Light Reflective Value (LRV) of less than 55 unless it is in the Benjamin Moore approved Colors for Vinyl palette and comports with the specific vinyl manufacturer guidelines when making the color selection and painting. Otherwise, the color will absorb more heat, possibly causing the siding to warp, resulting in additional repairs and expenses.

Rough or Pitted Masonry:

Primer: Ultra Spec[®] Hi-Build Masonry Block Filler (571)

Finish: 1 or 2 coats Regal® Select Exterior Paint - MoorLife® Flat Finish (W105) Poured or Pre-cast Concrete and Fiber Cement Siding:

Primer: No primer needed

Finish: 2 coats Regal[®] Select Exterior Paint – MoorLife[®] Flat Finish (W105) Ferrous Metal (Steel and Iron):

Primer: Ultra Spec® HP Acrylic Metal Primer (HP04) or Super Spec HP® Alkyd Metal Primer (P06)

Finish: 1 or 2 coats Regal® Select Exterior Paint - MoorLife® Flat Finish (W105) Non-Ferrous Metal (Galvanized & Aluminum):

All new metal surfaces must be thoroughly cleaned with an Oil & Grease Emulsifier Corotech® V600 to remove contaminants. New shiny non-ferrous metal surfaces that will be subject to abrasion should be dulled with very fine sandpaper or a synthetic steel wool pad to promote adhesion. Primer: No primer needed

Finish: 2 coats Regal[®] Select Exterior Paint – MoorLife[®] Flat Finish (W105) Repaint, All Substrates: Prime bare areas with the primer recommended for the substrate above.

Application

Stir thoroughly before and during use. Apply one or two coats. For best results, use a Benjamin Moore® custom-blended nylon/polyester brush, Benjamin Moore[®] roller, or a similar product. This product can also be sprayed.

Spray, Airless: Fluid Pressure — 1,500 to 2,500 PSI; Tip — .013 - .017 Orifice

Thinning/Clean Up

Thinning is unnecessary, but if required to obtain desired application properties, a small amount of clean water may be added. Never add other paints or solvents. Clean up with warm soapy water. Brushes should be given an additional quick rinse with mineral spirits if compliant with local requirements, followed by a second wash in soapy water, then rinsed thoroughly. Spray equipment should be given a final rinse with mineral spirits to prevent rusting if compliant with local requirements.

Conditioning with Benjamin Moore [®] 518 Extender may be necessary under certain conditions to adjust open time or spray characteristics. The chart below is for general guidance			
	Mild conditions	Severe Conditions	
	Humid (RH> 50%) with no direct sunlight & with little to no wind	Dry (RH<50%), in direct sunlight, or windy conditions	
Brush: Nylon / Polyester	No thinning necessary	Add 518 Extender or	
Roller: Premium Quality		water: Max of 8 fl. oz. to a	
Spray: Airless Pressure: 1500-2500 psi Tip: .013017		gallon of paint Never add other paints or solvents.	

USE COMPLETELY OR DISPOSE OF PROPERLY. Dry empty containers may be recycled in a can recycling program. Local disposal requirements vary; consult your sanitation department or state-designated environmental agency on disposal options.

Environmental Health & Safety Information

WARNING

Cancer Hazard. Contains Crystalline Silica that can cause cancer when in respirable form (spray mist or sanding dust).

Use only with adequate ventilation. Do not breathe spray mist or sanding dust. Ensure fresh air entry during application and drying. Avoid contact with eyes and prolonged or repeated contact with skin. Avoid exposure to dust and spray mist by wearing a NIOSH approved respirator during application, sanding and clean up. Follow respirator manufacturer's directions for respirator use. Close container after each use. Wash thoroughly after handling.



FIRST AID: In case of eye contact, flush immediately with plenty of water for at least 15 minutes; for skin, wash thoroughly with soap and water. If symptoms persist, seek medical attention. If you experience difficulty breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical attention immediately.

IN CASE OF SPILL - Absorb with inert material and dispose of as specified under "Clean Up".

KEEP OUT OF REACH OF CHILDREN PROTECT FROM FREEZING

Refer to Safety Data Sheet for additional health and safety information.

Benjamin Moore & Co., 101 Paragon Drive, Montvale, NJ 07645 Tel: (201) 573-9600 www.benjaminmoore.com M72 W105 US 070621 Benjamin Moore, Gennex, Fresh Start, Moorlife, Regal, Super Spec, Super Spec HP, Ultra Spec and the triangle "M" symbol are registered trademarks, licensed to Benjamin Moore & Co. © 2006, 2021 Benjamin Moore & Co. All other trademarks belong to their respective owners. All rights reserved