Benjamin Moore[,]



Features

- High-solids content
- Outstanding protection
 against corrosion
- Engineered for use in general metal finishing and fabrication
- Also appropriate for chemical processing facilities and transportation infrastructure finishing
- Suitable as a highperformance tie coat; especially over existing epoxies

Recommended For

Properly prepared Steel, Iron, Galvanized, Aluminum, and other nonferrous metals. Corotech® CV150 Polyamide Epoxy is a multi-use epoxy primer for metal in the industrial maintenance market, food and beverage processing market, general metal finishing and fabrication market, chemical processing market, as well as transportation infrastructure finishing or other areas requiring a two-component, corrosion resistant primer for metal.

POLYAMIDE EPOXY PRIMER CV150

General Description

Polyamide Epoxy Primer is formulated for use on ferrous and nonferrous metals in industrial and commercial applications. This epoxy primer is an excellent choice for use as a rust-inhibitive base coat when used as part of a high-performance coating system. With proper top coating, it demonstrates excellent resistance to moisture and chemicals, including solvents, acids, and alkalis. Polyamide Epoxy Primer is also suitable for use on concrete substrates in secondary containment and immersion service applications. This is a two-component product that requires 1 part of the proper "A" component mixed with 1 part of part "B" catalyst. The components are already premeasured to the proper mix ratio. No measuring required. Do not mix partial kits.

Limitations

- Do not apply at ambient or surface temperatures below 50 °F (10 °C).
- Do not paint if surface temperature is within 5 degrees of the dew point or if rain is expected within 12 hours.

	P	roduct Inform	ation			
Colors — Standard:			Technical Data◊		Red	
Red (20), Gray (70)			Generic Type		Polyamide Epoxy	
			Pigment Type		Titanium Dioxide	
— Tint Bases:			Volume Solids (mixed as recommended) 62 ± 1.0%			
Do not tint.			Coverage per Gallon at			
			Recommended Film Thic		350 – 400 Sq. Ft.	
— Special Colors:			Recommended	-Wet	4.0 – 4.5 mils	
Contact your retailer.			Film Thickness	– Dry	2.4 – 2.8 mils	
			Depending on surface texture and porosity. Be sure to estimate right amount of paint for the job. This will ensure color uniformity a			
Certifications & Qualifications:			minimize the disposal of excess paint.			
CEI UNICAUVIIS & QUAINICAUVIIS.				– To Touch	2 Hours	
The product supported by this data sheet contains a maximum of 250 grams per liter VOC / VOS (2.08 lbs. /gal.) excluding water & exempt solvents Meets performance requirements of MIL-P-53022 & MIL-P-23377 Meets SSPC Paint 22 (Primer) Suitable for use in USDA Inspected Facilities		COMPLIANT	(25°C) @ 50% KH	– To Recoat 8 Ho	ours / Max 4 weeks	
	VOC REGION	YES		– To Cure	3 – 4 Days	
	OTC	YES	*If top coat is not applied y	*If top coat is not applied within 72 hours abrade the surface to ensure proper inter-coat adhesion. Maximum abrasion and chemical resistance are achieved at full cure; care should be taken to prevent		
	OTC	YES	proper inter-coat adhes			
	CARB	YES				
	CARB CARB07	YES	damage to the coating during the curing process. High humidity and cool temperatures will result in longer dry, recoat and cure times.			
	UTAH	YES	Dries By	s By Chemical Cure		
	AZMC	YES	Dry Heat Resistance		275 °F	
	SCAQMD	NO	Viscosity @ 77 °F (mixed	d as recommended)	85 – 95 KU	
	SCAQIND	NO	Flash Point	ash Point Mixed: 80 °F. (TT-P-141, Method 42		
Technical Assistance:			Gloss/Sheen	Low She	een (5 - 10 @ 60°)	
Available through your local authorized indep	pendent Benjar	nin Moore	Surface Temperature	– Min.	50 °F	
retailer. For the location of the retailer nearest you, call 1-866-708-9180 or visit <u>www.benjaminmoore.com</u>			at application	– Max.	90 °F	
			Surface must be dry and at least 5° above the dew point			
			Thin With		Do Not Thin	
			Clean Up Thinner	Corotech [®] V7	04 Epoxy Reducer	
			Mixed Ratio (by volume) 1:1			
					30 Minutes	
					4 Hours	
			Weight Per Gallon (mixe	,	13.1 lbs.	
			Storage Temperature	– Min.	40 °F	
				– Max.	90 °F	
			Volatile O 247 Grams /	rganic Compounds (Vo Liter* 2.06 LBS / C * Catalyzed		
			Reported values are for	r Pod. Contact rotailor f	or voluce of other	

◊ Reported values are for Red. Contact retailer for values of other bases or colors.

Surface Preparation

All surfaces must be sound, dry, clean and free of oil, grease, dirt, mildew, mill scale, form release agents, curing compounds, loose and flaking paint and other surface contaminants.

NEW SURFACES: Concrete and Masonry: All masonry surfaces must be allowed to cure a minimum of 30 days before painting. Acid etch or abrasive blast all slick, glazed concrete or concrete with laitance. For acid etching, follow all manufacturer's directions and safety instructions. Rinse thoroughly and allow to dry. Prime concrete with one coat of V155 100% Solid Epoxy Pre-Primer.

Steel and Ferrous Metals: All direct to metal coatings provide maximum performance over near white metal blasted surfaces (SSPC-SP 10). There are however, situations and cost There are however, situations and cost considerations that may prevent this type of surface preparation from being done. Corotech® Industrial Coatings have been designed to provide protection over less than ideal surfaces. The recommended standard is a commercial blast (SSPC-SP 6). The steel profile after the blast should be 1-2 mils and be jagged in nature. Surfaces must be free of grit dust. The coating should be applied as soon as possible after the blast in order to prevent flash rusting or surface contamination. Hand tool cleaning (SSPC-SP 2) or power tool cleaning (SSPC-SP 3) can be used if blasting is not possible. In areas where adequate surface preparation is not possible the use of V155 100% Solid Epoxy Pre-Primer is recommended. In highly corrosive areas where additional rust inhibitive qualities are required, prime with one coat of V170 Organic Zinc Rich Primer prior to applying epoxy coatings.

Galvanized and Non-Ferrous Metals: Solvent clean all surfaces. Self-Priming or apply one coat of Corotech[®] V110 Acrylic Metal Primer or V175 Waterborne Bonding Primer.

Previously Painted Surfaces: Can be applied over most old industrial finishes in good condition. Test patches are recommended to check for wrinkling or lifting of existing coatings. V155 100% Solid Epoxy Pre-Primer may be used as a barrier coat over all existing coatings.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Informational Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Application

Mixing Instructions:

This is a two component kit and is pre-proportioned for error free mixing. DO NOT vary from these instructions. Mix "A" & "B" separately

- Carefully empty the entire contents of CV150-90 activator into the can of CV150-Part A component resin; scrape the sides of the pail of Part B to make sure all liquid has been added. Part A container is oversized to completely accept entire contents of Part B material.
- Using a jiffy mixer at low speed, blend this mixture for three to five minutes until completely blended. Keep the mixing blade turning at a slow speed to minimize whipping air into material. Scrape sides of pail during the mixing process.
- 3. Care must be taken to assure both components are completely mixed in order to avoid partially cured spots in the coating.
- 4. Allow to induct for 30 minutes.

Do not thin this product – it is ready to use once both components are thoroughly mixed.

It is extremely important to remember that Epoxy Coatings have a limited pot life. Therefore, it is wise to make sure sufficient manpower and correct application tools are in order prior to starting the mixing sequence.

Application:

Airless Spray (Preferred Method): Tip range between .017 and .021. Total fluid output pressure at tip should not be less than 2100 psi.

Air Spray (Pressure Pot): DeVilbis MBC or JGA gun, with 704 or 765 air cap and Fluid Tip E.

Brush: Natural Bristle only. / **Roller:** Industrial Cover with Phenolic core. $\chi_1^{n} - \chi_2^{n}$ nap.

NOTE: Do not allow material to remain in hoses, gun or spray equipment. Thoroughly flush all equipment with recommended thinner. No reduction is necessary. This product will not cure at surface temperatures below 50 °F (10 °C). Do not apply if material, substrate or ambient temperature is below 50 °F (10 °C). Relative humidity should be below 90%. Do not apply if within 5 degrees of dew point or if rain is expected within 12 hours of application.

Notes: All high gloss surfaces can be slippery. Where non-skid properties are required a non-skid additive should be used.

All epoxy coatings will chalk and fade if applied on exterior surfaces subjected to direct sunlight. All epoxies tend to yellow. Where color and gloss retention is important top-coating will be necessary. Will stain with prolonged exposure to some solvents and chemicals or in kennels if exposed to animal waste. This staining will not affect the durability or protective qualities of the coating.

TEST DATA					
Sag Resistance (ASTM D4400)	8 mils +				
Flexibility (ASTM D1737)	Pass 1/4" (6.35 mm) Mandrel				
Steam Resistant	Yes				
Dry Heat Resistance	275 °F (135 °C)				
Wet Heat Resistance	150 °F (65.56 °C)				
Adhesion (ASTM D3359)	Pass 5B				
Humidity (ASTM D4585) (1 Coat	Face Corrosion: None				
w/2 cts. V400 Topcoat, 6 mils,	Face Blistering: None				
1000 Hours)	Rating: 10, Rust: 0.00%				
Salt Spray (ASTM B117) (1 Coat w/2 cts. V400 Topcoat, 6 mils, 600 Hours)	Face Corrosion: None Face Blistering: None Rating: 10, Rust: 0.00%				
CHEMICAL RESISTANCE GUIDE (NON-IMMERSION)					
Fresh Water					
Salt Water					
Acids					
Alkalis	See Finish Coat Data Sheets				
Solvents	for Resistance Information.				
Fuel					
Acidic Salt Solutions					
Alkaline Salt Solutions					
Neutral Salt Solutions					

SYSTEMS RECOMMENDATIONS COMPATIBLE FINISHES V200 Line, V201, V230 Line, V231 Line, V220 Line, V300 Line, V330 Line, V400 Line, V410, V430 Line, V440 Line, V500 Line, V510 Line, V520 Line, 540 Line, and Other Alkyds, Acrylics and Moisture Cured Urethanes For substrates other than listed above, or for usage in severe environmental conditions, please consult with Corotech® Technical Service.

Clean Up

Clean up with Corotech® V704 Epoxy Reducer.

Environmental Health & Safety Information

Danger Causes skin irritation Causes serious eye irritation May cause an allergic skin reaction May cause cancer May damage fertility or the unborn child Causes damage to organs Causes damage to organs through prolonged or repeated exposure May be fatal if swallowed and enters airways Flammable liquid and vapor

Prevention: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Wash face, hands and any exposed skin thoroughly after handling. Contaminated work clothing should not be allowed out of the workplace. Do not breathe dust/fume/mist/vapors/spray. Do not eat, drink or smoke when using this product. Keep away from heat/sparks/open flames/hot surfaces, no smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof electrical/ ventilating/ lighting/equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Wear protective gloves/ protective clothing/eye protection/face protection.

Response: If exposed call a POISON CENTER or physician. If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists get medical attention. If skin irritation or rash occurs get medical attention. If on skin (or hair) take off immediately all contaminated clothing. Rinse skin with water. Wash contaminated clothing before reuse. If swallowed immediately call a POISON CENTER or physician. Do NOT induce vomiting. In case of fire use CO2, dry chemical, or foam for extinction.

Storage: Store locked up. Store in a well-ventilated place. Keep cool.

Disposal: Dispose of contents/container to an approved waste disposal plant.

IMPORTANT: Designed to be mixed with other components. Mixture will have hazards of all components. Before opening packages, read all warning labels. Follow all precautions.

CAUTION: All floor coatings may become slippery when wet. Where non-skid characteristics are desired, a small amount of clean sand may be added. Stir often during application.

WARNING Cancer and Reproductive Harm www.P65warnings.ca.gov

This document represents hazards of the product referenced above. Refer to the individual Safety Data Sheet for hazards of the specific product you will be using.

KEEP OUT OF REACH OF CHILDREN FOR PROFFESIONAL USE ONLY

Refer to Safety Data Sheet for additional health and safety information.

Benjamin Moore & Co., 101 Paragon Drive, Montvale, NJ 07645 Tel: 866-708-9180 Fax: 888-248-2143 www.benjaminmoore.com M72 CV150 EN 081618 ©2017, 2018 Benjamin Moore & Co. Benjamin Moore and the triangle "M" symbol are registered trademarks licensed to Benjamin Moore & Co. All other marks are the property of their respective owner. All rights reserved