Benjamin Moore



Hard, scratch- and

High-solids formula

impact-resistant coating

Features

- Urethane modification for maximum durability
- Easy application
- For use on most surfaces

Recommended For

Corotech[®] Alkyd Urethane Enamel Gloss is intended for use as an interior and exterior coating on a wide variety of surfaces, such as previously painted surfaces, ferrous metal and drywall. It is most commonly used in industrial or professional applications. This product is not recommended for direct application to non-ferrous metals such as galvanized metal or aluminum unless primed with V110 Acrylic Metal Primer.

ALKYD URETHANE ENAMEL GLOSS V200

General Description

V200 product is a heavy-duty alkyd enamel intended for use on a wide variety of surfaces, both interior and exterior. The surfacetolerant formula sticks to surfaces that may be marginally prepared, and the exceptional flow and leveling provides a smooth, uniform finish. Made with our toughest alkyd resin, this paint stands up to mechanical and human abuse, while the urethane fortification adds gloss and color retention in exterior spaces exposed to sunlight and rain.

Limitations

- Do not apply if material, substrate or ambient temperature is below 50 °F (10 °C). Relative humidity should be below 90%.
- Do not apply directly to galvanized metal.
- Not for immersion service.
- DO NOT topcoat with products such as epoxies or urethanes containing aromatic or oxygenated solvents.

Colors — Standard:			Technical Data◊		White
White (01), Safety Yellow (10), Safety Red (20), Safety Blue (30), Safety Green (40), Bronzetone (62) – <i>Satin Finish</i> , Silver Gray (70), Battleship Gray (75), Black (80), Wrought Iron Black (81) – <i>Flat Finish</i>			Vehicle Type		Modified Alkyc
			Pigment Type		Titanium Oxide
			Volume Solids		56 ± 1.0%
— Tint Bases: Pastel Base (85), Tint Base (86), Deep Base (87), Clear Base (88).			Coverage per Gallon at Recommended Film Thi	ckness	400 – 450 Sq. Ft
Tint with Universal Colorants			Recommended Film Thickness	– Wet – Dry	3.6 – 4.0 mils 2.0 - 2.2 mils
— Special Colors:			Depending on surface estimate the right amount color uniformity and minim	of paint for the	job. This will ensure
Contact your retailer Certifications & Qualifications:			Dry Time @ 77 °F (25 °C) @ 50% RH	 – Tack Free – To Recoa – Full Cure 	
The products supported by this data sheet			High humidity and cool te recoat and service times.	mperatures will	1
contain a maximum of 340 grams per liter VOC / VOS (2.83 lbs. /gal.) excluding water	VOC REGION	COMPLIANT	Dries By	Oxidation	
& exempt solvents.	FEDERAL	YES	Viscosity		80 – 85 Kl
Masters Painters Institute MPI # 9, 27 & 48.	OTC	YES	Flash Point	104 °F (TT-P	-141, Method 4293
V200 meets performance requirements of TT-E-487E, -489J, -491C, -496 (Type II), - 506K, -1593 and -2784A	OTCII	NO	Gloss/Sheen Wrought Iron Black - Flat (0-5 @ 60		
	CARB	NO			· ·
V200-80 meets performance requirements of SSPC Paint #102	CARB07	NO	Surface Temperature	– Min.	, 50 °l
	UTAH	NO	at Application	– Max.	100 °I
V200 meets performance requirements of MIL-E-20090 and -15090 Type I	AZMC SCAQMD	YES	Thin With		Do Not Thi
Suitable for use in USDA inspected facilities			Clean Up Thinner	V70 ⁻	Brushing Reduce or Mineral Spirits
Technical Assistance:			Weight Per Gallon		9.8 Lbs
Available through your local authorized independent Benjamin Moore retailer. For the location of the retailer nearest you, call 1-866-708-9180 or visit www.benjaminmoore.com			Storage Temperature	<u>– Min.</u> – Max.	45 °I 95 °I
<u></u>			Volatile Orga	nic Compoun	ds (VOC)
			335 Grams/L	iter 2.8 Lbs	./Gallon

Surface Preparation

The performance of this product is directly dependent upon the degree of surface preparation employed. All Grease Oil, Dirt, Mildew, or any other surface contaminants must be removed using Corotech V600 Oil & Grease Emulsifier.

Ferrous Metal: All rust and mill scale should be removed prior to application of this product. This is best accomplished by abrasive blasting. A minimum of SSPC-SP 6 Commercial Blast is recommended for severe environmental exposures. Small areas may be cleaned in accordance with SSPC-SP 2 Hand Tool Cleaning or SSPC-SP 3 Power Tool Cleaning or SSPC-SP 11 Power Tool Cleaning to Bare Metal. It is recommended that the prepared ferrous metal be primed for best corrosion resistance.

Non-Ferrous Metals: Solvent Clean or use Corotech[®] V600 Oil & Grease Emulsifier in accordance with SSPC-SP1. The use of an Acrylic or Phenolic Alkyd primer on non-ferrous metals is recommended.

Concrete: Form release agents and curing compounds must be removed prior to coating. The concrete to be coated must be opened to enable coating penetration; this may be accomplished by acid washing or abrasive blasting. Coarse masonry should be primed with appropriate block filler.

Plaster and Dry Wall: Prime new drywall and cured plaster with a quality acrylic primer. Apply one or two finish coats as needed.

For use on substrates other than specified above, please contact our Technical Service Department.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

TEST DATA			
Flexibility (ASTM D1737)	Pass 1/4" (6.35 mm) Mandrel		
Dry Heat Resistance	275 °F (135 °C)		
Wet Heat Resistance	150 °F (65.56 °C)		
Adhesion (ASTM D3359)	Pass 5B		
Salt Fog Resistance (ASTM B117) Two coats over V140 Line primer	500 Hours-Pass (Rating 10, Rust Area 0.00%)		
Accelerated Weather (ASTM G53)	70% Retention after 500 Hrs.		
Abrasion Resistance (ASTM D4060)-CS10 Wheel	120mg loss after 1000 cycles		

CHEMICAL RESISTANCE GUIDE (NON-IMMERSION)			
Fresh Water	Excellent		
Salt Water	Good		
Acids	Fair		
Alkalis	Fair		
Solvents	Fair		
Fuel	Fair		
Acidic Salt Solutions	Good		
Alkaline Salt Solutions	Good		
Neutral Salt Solutions	Good		

SYSTEMS RECOMMENDATIONS COMPATIBLE PRIMERS V110 Line, V114, V130, V131 Line, V132 Line, V133 Line, V140 Line, V142 Line, V155, V150 Line, V160 Line, V163, V175, V180 and other acrylic and alkyd primers

Application

Mix the product thoroughly before application. The use of a drill mixer at low speed will best accomplish this.

Airless Spray: Tip range between .013 and .017. Total fluid output pressure at tip should not be less than 2200 psi.

Air Spray (Pressure Pot): DeVilbis MBC or JGA gun, with 704 or 765 air cap and Fluid Tip E.

Brush / Roller: Can be brushed using a natural bristle brush or rolled using a 3/8" lambs wool or 1/4" - 1/2" synthetic roller cover. Roll in one direction, rewet, then cross roll.

NOTE: Do not allow material to remain in hoses, gun or spray equipment. Thoroughly flush all equipment with recommended thinner. No reduction is necessary. Do not apply if material, substrate or ambient temperature is below 50 °F (10 °C). Relative humidity should be below 90%. Do not apply if within 5 degrees of dew point or if rain is expected within 12 hours of application.

Clean Up

Clean with V701 Brushing Reducer or Mineral Spirits.

Environmental Health & Safety Information DANGER!

May cause an allergic skin reaction

Suspected of causing cancer

Causes damage to organs through prolonged or repeated exposure

May be fatal if swallowed and enters airways

Flammable liquid and vapor

Prevention: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Contaminated work clothing should not be allowed out of the workplace. Wear protective gloves. Do not breathe dust/fume/mist/vapors/spray. Wash face, hands and any exposed skin thoroughly after handling. Do not eat, drink or smoke when using this product. Keep away from heat/sparks/open flames/hot surfaces, no smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use only non-sparking tools. Take precautionary measures against static discharge.

Response: If exposed or concerned get medical attention. If skin irritation or rash occurs get medical attention. Wash contaminated clothing before reuse. If on skin (or hair) take off immediately all contaminated clothing. Rinse skin with water. If swallowed immediately call a POISON CENTER or physician. Do NOT induce vomiting. In case of fire use CO2, dry chemical, or foam for extinction.

Storage: Store locked up. Store in a well-ventilated place. Keep cool.

Disposal: Dispose of contents/container to an approved waste disposal plant.

DANGER - Rags, steel wool or waste soaked with this product may spontaneously catch fire if improperly discarded. Immediately after use, place rags, steel wool or waste in a sealed water-filled metal container.

WARNING Cancer and Reproductive Harmwww.P65warnings.ca.gov

This document represents hazards of the product referenced above. Refer to the individual Safety Data Sheet for hazards of the specific product you will be using.

KEEP OUT OF REACH OF CHILDREN FOR PROFESSIONAL USE ONLY

Refer to Safety Data Sheet for additional health and safety information.

Benjamin Moore & Co., 101 Paragon Drive, Montvale, NJ 07645 Tel: 866-708-9180 Fax: 888-248-2143 <u>www.benjaminmoore.com</u> M72 V200 EN 122018 ©2017, 2018 Benjamin Moore & Co. Benjamin Moore and the triangle "M" symbol are registered trademarks licensed to Benjamin Moore & Co. All other marks are the property of their respective owner. All rights reserved