



MURESCO[®] CEILING WHITE 258

Features

- Uniform flat finish that tones down ceiling glare
- Excellent hide
- Resists spattering
- Easy application
- Low VOC
- Good sprayability

General Description

A premium quality, acrylic coating that delivers excellent hide, rolls and sprays on smoothly, resists spatter and offers extended open time for an easier, more efficient application. Ideal on most types of interior ceilings, including textured ceilings.

Recommended For

Residential or commercial ceiling applications where a premium quality finish is desired. For new or previously painted wallboard, wallpapered surfaces, acoustical ceiling tile, textured ceilings, cured masonry, plaster, and other ceiling substrates.

Limitations

- Do not apply when air and surface temperatures are below 50 °F (10 °C)
- Not for high traffic areas or surfaces that require frequent cleaning

Product Information

| Product Information | | White | |
|---|--|--------------------------|----------------|
| Colors — Standard: White (01), Classic Ceiling White (04) | Technical Data[◇] | | |
| — Tint Bases: N/A | Vehicle Type | Acrylic Latex | |
| — Special Colors: N/A | Pigment Type | Titanium Dioxide | |
| Certifications & Qualifications: VOC compliant in all regulated areas | Volume Solids | 31% | |
| Technical Assistance Available through your local authorized independent Benjamin Moore retailer. For the location of the retailer nearest you, call 1-866-708-9180 or visit www.benjaminmoore.com | Coverage per Gallon at Recommended Film Thickness | 400 – 450 Sq. Ft. | |
| | Recommended Film Thickness | – Wet | 3.5 – 4.1 mils |
| | | – Dry | 1.1 – 1.3 mils |
| | Depending on surface texture and porosity. Be sure to estimate the right amount of paint for the job. This will ensure color uniformity and minimize the disposal of excess paint. | | |
| | Dry Time @ 77 °F (25 °C) @ 50% RH | – To Touch | 1 Hour |
| | | – To Recoat | 2 Hours |
| | Painted surfaces can be washed after two weeks. High humidity and cool temperatures will result in longer dry, recoat and service times. | | |
| | Dries By | Evaporation, Coalescence | |
| | Viscosity | 103 ± 5 KU | |
| | Flash Point | None | |
| | Gloss / Sheen | Flat (2 – 5 @ 85°) | |
| | Surface Temperature at Application | – Min. | 50 °F |
| | | – Max. | 90 °F |
| | Thin With | See Chart | |
| | Clean Up Thinner | Clean Water | |
| | Weight Per Gallon | 11.4 lbs | |
| | Storage Temperature | – Min. | 40 °F |
| | | – Max. | 90 °F |
| | Volatile Organic Compounds (VOC) | | |
| | 47.8 Grams/Liter | .40 lbs./Gallon | |

Surface Preparation

Surfaces to be painted must be clean, dry, and free of dirt, dust, grease, oil, soap, wax, scaling paint, water soluble materials, and mildew. Remove any peeling or scaling paint and sand these areas to feather edges smooth with adjacent surfaces. Glossy areas should be dulled. Drywall surfaces must be free of sanding dust.

New plaster or masonry surfaces must be allowed to cure (30 days) before applying base coat. Cured plaster should be hard, have a slight sheen and maximum pH of 10; soft, porous or powdery plaster indicates improper cure. Never sand a plaster surface; knife off any protrusions and prime plaster before and after applying patching compound.

Poured or pre-cast concrete with a very smooth surface should be etched or abraded to promote adhesion, after removing all form release agents and curing compounds. Remove any powder or loose particles before priming.

Difficult Substrates: Benjamin Moore offers a number of specialty primers for use over difficult substrates such as bleeding woods, grease, crayon markings, hard glossy surfaces, galvanized metal, or other substrates where paint adhesion or stain suppression is a particular problem. Your Benjamin Moore retailer can recommend the right problem solving primer for your special needs.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Informational Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Primer/Finish Systems

New surfaces should be fully primed, and previously painted surfaces may be primed or spot primed as necessary. For best hiding results, tint the primer to the approximate shade of the finish coat, especially when a significant color change is desired. Consult your retailer.

Wood, and engineered wood products:

Primer: Fresh Start® High-Hiding All Purpose Primer (046)

Finish: 1 or 2 coats Muresco® Ceiling White (258)

Drywall:

Primer: Fresh Start® High-Hiding All Purpose Primer (046) or this product

Finish: 1 or 2 coats Muresco® Ceiling White (258)

Plaster:

Primer: Fresh Start® High-Hiding All Purpose Primer (046)

Finish: 1 or 2 coats Muresco® Ceiling White (258)

Rough or Pitted Masonry:

Primer: Ultra Spec® Masonry Interior/Exterior Hi-Build Block Filler (571)

Finish: 1 or 2 coats Muresco® Ceiling White (258)

Smooth Poured or Pre-cast Concrete:

Primer: Ultra Spec® Masonry Interior / Exterior 100% Acrylic Masonry Sealer (608)

Finish: 1 or 2 coats Muresco® Ceiling White (258)

Ferrous Metal (Steel and Iron):

Primer: Ultra Spec® HP Acrylic Metal Primer (HP04) or

Super Spec HP® Alkyd Metal Primer (P06)

Finish: 1 or 2 coats Muresco® Ceiling White (258)

Stippled ceiling note: Some types of stippled ceilings are water sensitive and require an alkyd primer sealer before applying the finish coat.

Primer: Fresh Start® Multi-Purpose Oil Based Primer (024)

Finish: 1 or 2 coats Muresco® Ceiling White (258)

Non-Ferrous Metal (Galvanized & Aluminum): All new metal surfaces must be thoroughly cleaned with Corotech® Oil & Grease Emulsifier (V600) to remove contaminants. New shiny non-ferrous metal surfaces that will be subject to abrasion should be dulled with very fine sandpaper or a synthetic steel wool pad to promote adhesion

Primer: Ultra Spec® HP Acrylic Metal Primer (HP04)

Finish: 1 or 2 coats Muresco® Ceiling White (258)

Repaint, All Substrates: Prime bare areas with the primer recommended for the substrate above.

Application

Mixing of Paint: Stir thoroughly before and occasionally during use. For best application results, apply generously going from unpainted into painted areas.

Thin with up to 8 fl. oz. of water or 518 Extender per gallon if needed.

Airless Spray: Tip range between .013 and .017. Total fluid output pressure at tip should be 1000-2000 psi.

Paint Application: For best results, use a premium Benjamin Moore® custom-blended nylon/polyester brush, premium Benjamin Moore® roller, or a similar product. Apply paint generously from unpainted area into wet area.

If your edge begins to dry or you see that you missed a spot and the paint is already setting up, allow it to dry completely before touching up that area.

Clean Up

USE COMPLETELY OR DISPOSE OF PROPERLY. Dry, empty containers may be recycled in a can recycling program. **Local disposal requirements vary; consult your sanitation department or state-designated environmental agency on disposal options.**

Environmental Health & Safety Information

Use only with adequate ventilation. Do not breathe spray mist or sanding dust. Ensure fresh air entry during application and drying. Avoid contact with eyes and prolonged or repeated contact with skin. Avoid exposure to dust and spray mist by wearing a NIOSH approved respirator during application, sanding and clean up. Follow respirator manufacturer's directions for respirator use. Close container after each use. Wash thoroughly after handling.



WARNING: This product can expose you to chemicals including Methyl isobutyl ketone, which are known to the State of California to cause cancer and birth defects or other reproductive harm. For more information go to www.P65warnings.ca.gov

WARNING: This product contains isothiazolinone compounds at levels of <0.1%. These substances are biocides commonly found in most paints and a variety of personal care products as a preservative. Certain individuals may be sensitive or allergic to these substances, even at low levels.

FIRST AID: In case of eye contact, flush immediately with plenty of water for at least 15 minutes; for skin, wash thoroughly with soap and water. If symptoms persist, seek medical attention. If you experience difficulty breathing, leave the area to obtain fresh air. If continued difficulty is experienced, get medical attention immediately.

IN CASE OF SPILL – Absorb with inert material and dispose of as specified under “Clean Up”

KEEP OUT OF REACH OF CHILDREN

PROTECT FROM FREEZING

Refer to Safety Data Sheet for additional health and safety information.