

Features

- Formulated for use over properly prepared /primed steel, iron, concrete, and nonferrous metal
- Provides excellent protection from water, acids, alkalis, and mild solvents
- Can be applied directly to the substrate; use with a primer for extra longevity

Recommended For

Properly prepared and/or primed Steel, Iron, Concrete, and nonferrous metals. V157 Coal Tar Epoxy is designed for the waste water treatment, chemical processing, pulp and paper, and industrial maintenance markets or anywhere a tar filled polyamide epoxy is required for excellent resistance to water, chemicals and underground exposures.

COAL TAR EPOXY BLACK V157

General Description

V157 Coal Tar Epoxy is a high solids, two component tar filled coating formulated to provide excellent film build in one or two coats. The high level of cross-linking provides an excellent barrier coat for immersion service in fresh water, salt water or waste water. Additionally, this product is resistant to many acids, alkalis and mild solvents in splash and spill exposures. The high build of this product provides an excellent non-conductive film for use between dissimilar metals. This product may be applied direct to prepared ferrous metal and concrete. This is a two-component product that requires 4 parts of the V157-80 "A" Component mixed with 1 part of the V157-90 "B" Component. Mix ratio is 4:1. Do not mix partial kits.

Limitations

- Do not apply if material, substrate or ambient temperature is below 10 °C (50 °F). Relative humidity should be below 90%.
- Do not apply if within 5 degrees of dew point or if rain is expected within 12 hours of application.

Colours — Standard: Black (80) — Tint Bases: N/A Do not tint. — Special Colours: Contact your retailer. Certification:	coat adhesion. Maximum abrasion an	6.5 – 12.5 sq. m. (70 - 135 sq. ft.) 12 – 23 mils 8.5 - 16.5 mils
Black (80) — Tint Bases: N/A Do not tint. — Special Colours: Contact your retailer.	Generic Type Pigment Type Volume Solids (mixed as recommer Coverage per 3.79 L at Recommended Film Thickness Recommended — Wet Film Thickness — Dry Depending on surface texture and public per 3.70 L at Coverage per 3.79 L at Recommended — Wet Film Thickness — Dry Depending on surface texture and public per 3.70 L at 1.70 Touch To Recoat Full Cure *If top coat is not applied within 72 hour coat adhesion. Maximum abrasion and	Polyamide Epoxy Coal Tar anded) 70% ± 1.0% 6.5 – 12.5 sq. m. (70 - 135 sq. ft.) 12 – 23 mils 8.5 - 16.5 mils porosity. 2 Hours 12 Hours – Max: 72 Hours 3 - 7 Days
— Tint Bases: N/A Do not tint. — Special Colours: Contact your retailer.	Pigment Type Volume Solids (mixed as recomme Coverage per 3.79 L at Recommended Film Thickness Recommended — Wet Film Thickness — Dry Depending on surface texture and p Dry Time @ 25° C — To Touch (77°F) — To Recoat — Full Cure *If top coat is not applied within 72 hour coat adhesion. Maximum abrasion an	Coal Tai ended) 70% ± 1.0% 6.5 – 12.5 sq. m (70 - 135 sq. ft.) 12 – 23 mils 8.5 - 16.5 mils porosity. 2 Hours 12 Hours – Max: 72 Hours 3 - 7 Days
N/A Do not tint. — Special Colours: Contact your retailer.	Volume Solids (mixed as recomme Coverage per 3.79 L at Recommended Film Thickness Recommended — Wet Film Thickness — Dry Depending on surface texture and purchase (77 °F) — To Touch — To Recoat — Full Cure *If top coat is not applied within 72 hour coat adhesion. Maximum abrasion and	ended) 70% ± 1.0% 6.5 – 12.5 sq. m (70 - 135 sq. ft.) 12 – 23 mils 8.5 - 16.5 mils porosity. 2 Hours 12 Hours – Max: 72 Hours 3 - 7 Days
N/A Do not tint. — Special Colours: Contact your retailer.	Coverage per 3.79 L at Recommended Film Thickness Recommended — Wet Film Thickness — Dry Depending on surface texture and p Dry Time @ 25° C (77°F) — To Touch — To Recoat — Full Cure *If top coat is not applied within 72 hour coat adhesion. Maximum abrasion an	6.5 – 12.5 sq. m (70 - 135 sq. ft.) 12 – 23 mils 8.5 - 16.5 mils porosity. 2 Hours 12 Hours – Max: 72 Hours 3 - 7 Days
N/A Do not tint. — Special Colours: Contact your retailer.	Recommended Film Thickness Recommended — Wet Film Thickness — Dry Depending on surface texture and purchased provided	(70 - 135 sq. ft.) 12 - 23 mils 8.5 - 16.5 mils corosity. 2 Hours 12 Hours – Max: 72 Hours 3 - 7 Days
Do not tint. — Special Colours: Contact your retailer.	Recommended — Wet Film Thickness — Dry Depending on surface texture and p Dry Time @ 25° C (77°F) — To Touch — To Recoat — Full Cure *If top coat is not applied within 72 hour coat adhesion. Maximum abrasion an	12 – 23 mils 8.5 - 16.5 mils porosity. 2 Hours 12 Hours – Max: 72 Hours 3 - 7 Days
— Special Colours: Contact your retailer.	Film Thickness — Dry Depending on surface texture and properties (77°F) Dry Time @ 25°C — To Touch — To Recoat — Full Cure *If top coat is not applied within 72 hour coat adhesion. Maximum abrasion an	8.5 - 16.5 mils porosity. 2 Hours 12 Hours – Max: 72 Hours 3 - 7 Days
Contact your retailer.	Film Thickness — Dry Depending on surface texture and properties (77°F) Dry Time @ 25°C — To Touch — To Recoat — Full Cure *If top coat is not applied within 72 hour coat adhesion. Maximum abrasion an	8.5 - 16.5 mils porosity. 2 Hours 12 Hours – Max: 72 Hours 3 - 7 Days
,	Depending on surface texture and p Dry Time @ 25° C	oorosity. 2 Hours 12 Hours – Max: 72 Hours 3 - 7 Days
,	Dry Time @ 25° C — To Touch (77°F) — To Recoat — Full Cure *If top coat is not applied within 72 hour coat adhesion. Maximum abrasion an	2 Hours 12 Hours – Max: 72 Hours 3 - 7 Days
Certification:	Dry Time @ 25° C (77°F) — To Recoat — Full Cure *If top coat is not applied within 72 hour coat adhesion. Maximum abrasion an	12 Hours – Max: 72 Hours 3 - 7 Days
	(77 °F) — Full Cure *If top coat is not applied within 72 hour coat adhesion. Maximum abrasion an	3 - 7 Days
	*If top coat is not applied within 72 hour coat adhesion. Maximum abrasion an	
The products supported by this data sheet contain a maximum of 250 grams per litre VOC / VOS excluding water & exempt solvents. This product is compliant as an Industrial Maintenance Coating.		d chemical resistance are achieved at full t damage to the coating during the curing eratures will result in longer dry, recoat and
	Dries By	Chemical Cure
This product is currently approved for use under MPI #35.	Dry Heat Resistance	121 °C (250 °F)
Meets Performance Requirements for Army Corps of Engineers C-200	Viscosity @ 25 °C (77 °F) (mixed a recommended)	ns 105 – 110 KU
Meets Performance Requirements for SSPC Paint 16	Flash Point 29.	.4 °C (85 °F). (TT-P-141, Method 4293)
Meets Performance Requirements for DOD-P-23236	Gloss/Sheen	3 – 5 (Units @ 16 °C [60 °F])
Meets State of Tennessee DOT requirements for Non-	Surface Temperature – Min.	10 °C (50 °F)
Penetrating Coal Tar Epoxy Sealer.	at application – Max.	32.2 °C (90 °F)
	Thin With	Do Not Thir
Technical Assistance: Available through your local authorized independent Benjamin	Clean Up Thinner	Corotech® V703 Xylene or Corotech® V704 Epoxy Reducer
Moore® retailer. For the location of the retailer nearest you, call	Mixed Ratio (by volume)	4 : 1
1-877-711-6830, or visit www.benjaminmoore.ca	Induction time @ 25 °C (77 °F)	30 Minutes
	Pot Life @ 25 °C (77 °F)	6 Hours
	Weight Per 3.79 L (mixed as recommended)	5 kg (11.0 lbs)
	Storage Temperature – Min.	7.2 °C (45 °F)
	Max.	35 °C (95 °F)
	250 Grar	c Compounds (VOC) ns / Litre* atalyzed

 $[\]Diamond$ Reported values are for Black. Contact retailer for values of other bases or colours.

Coal Tar Epoxy Black V157

Surface Preparation

The performance of this product is directly dependent upon the degree of surface preparation employed. All dirt, oils and accumulated salts must be removed prior to employing specific surface preparation methods. Solvent washing in accordance with SSPC-SP 1 will best accomplish this task.

Steel: Non-Immersion requires Hand Tool Cleaning (SSPC-SP 2) or Power Tool Cleaning (SSPC-SP 3) or for best results, Commercial Blast Cleaning (SSPC-SP 6) followed by the proper primer. May be applied direct to ferrous metal in atmospheric exposures. Immersion service requires Near White Metal Blast (SSPC-SP 10) followed by the proper primer.

Concrete: Must have form/release agents removed by pressure washing or other suitable methods. Acid etching or abrasive blasting may be required to properly open the surface. May be applied direct to concrete.

Non-Ferrous Metals: Solvent Wash (SSPC-SP 1) as indicated above. Rusted areas on galvanized metal should be removed by Hand Tool Cleaning (SSPC-SP 2) or Power Tool Cleaning (SSPC-SP 3). Non-Ferrous metals should be primed for best results.

Please consult your dealer for other surface preparations or for use in severe environments.

WARNING! If you scrape, sand, or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and a wet mop. Before you start, find out how to protect yourself and your family by logging onto Health Canada @ http://www.hc-sc.gc.ca/ewh-semt/contaminants/lead-plomb/asked_questions-questions-posees-eng.php.

Application

Mixing Instructions:

This is a two component kit and is pre-proportioned for error free mixing.

DO NOT vary from these instructions. Mix "A" & "B" separately.

- Carefully empty the entire contents of V157-90 activator into the can of V157-Part A component resin; scrape the sides of the pail of Part B to make sure all liquid has been added. Part A container is filled to completely accept entire contents of Part B material.
- Using a jiffy mixer at low speed, blend this mixture for three to five minutes until completely blended. Keep the mixing blade turning at a slow speed to minimize whipping air into material. Scrape sides of pail during the mixing process.
- Care must be taken to assure both components are completely mixed in order to avoid partially cured spots in the coating.
- 4. Allow to induct for 30 minutes.

Do not thin this product – it is ready to use once both components are thoroughly mixed. It is extremely important to remember that Epoxy Coatings have a limited pot life; therefore, it is wise to make sure sufficient manpower and correct application tools are in order prior to starting the mixing sequence.

Application:

Airless Spray (Preferred Method): A 30:1 pump (minimum) is required to adequately spray this product. Tip range between .025 and .031. Total fluid output pressure at tip should not be less than 2400 psi

Air Spray (Pressure Pot): Not recommended due to excessive amount of thinner necessary to atomize.

Brush: Stiff Natural Bristle only. / **Roller:** Industrial Cover with Phenolic core.

NOTE: Do not allow material to remain in hoses, gun or spray equipment. Thoroughly flush all equipment with recommended thinner. No reduction is necessary. Do not apply if material, substrate or ambient temperature is below 10 °C (50 °F). Relative humidity should be below 90%. Do not apply if within 5 degrees of dew point or if rain is expected within 12 hours of application.

	TEST DATA
Sag (ASTM D4400)	25 mils +
Flexibility (ASTM D1737(Pass 3.2 mm (1/8") Mandrel
Steam Resistance	Yes
Dry Heat Resistance	121 °C (250 °F)
Wet Heat Resistance	82.1 °C (180 °F)
Adhesion (ASTM D3359)	Pass 5B
Accelerated Weathering	500 hours, no change
(ASTM G53)	
Humidity (ASTM D4585)	Face Corrosion: None
2 coats over V150 Line	Face Blistering: None
primer (1000 Hours)	Rating: 10, Rust: 0.00%
Salt Spray (ASTM B117)	Face Corrosion: None
(2 Coats over V150	Face Blistering: None
(1000 Hours)	Rating: 10, Rust: 0.00%

CHEMICAL RESISTANCE GUIDE (NON-IMMERSION)		
Fresh Water	Excellent	
Salt Water	Excellent	
Waste Water	Excellent	
Acids	Good	
Alkalis	Good	
Solvents	Fair	
Fuel	Fair	
Acidic Salt Solutions	Good	
Alkaline Salt Solutions	Good	
Neutral Salt Solutions	Good	

SYSTEMS RECOMMENDATIONS		
COMPATIBLE PRIMERS		
V132 Line, V150 Line, V155 Line, V160 Line, V400-00, V430-00		
COMPATIBLE INTERMEDIATES		
V160 Line		
For substrates other than listed above, or for usage in severe environmental conditions, please consult with Corotech® Technical Service.		

Coal Tar Epoxy Black V157

Clean Up

Clean up with Corotech® V703 Xylene or V704 Epoxy Reducer

Environmental Health & Safety Information

DANGER!

Causes severe skin burns and eye damage May cause an allergic skin reaction May cause genetic defects

May cause cancer

May damage fertility or the unborn child

Causes damage to organs through prolonged or repeated exposure

May be fatal if swallowed and enters airways

Flammable liquid and vapor

Prevention: Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Use personal protective equipment as required. Do not breathe dust/fume/mist/vapors/spray. Wash face, hands and any exposed skin thoroughly after handling. Contaminated work clothing should not be allowed out of the workplace. Wear protective gloves. Do not eat, drink or smoke when using this product. Keep away from heat/sparks/open flames/hot surfaces, no smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof electrical/ ventilating/ lighting/ equipment. Use only non-sparking tools. Take precautionary measures against static discharge.

Response: Immediately call a POISON CENTER or physician. If in eyes rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER or physician. If on skin (or hair) take off immediately all contaminated clothing. Rinse skin with water. Wash contaminated clothing before reuse. If skin irritation or rash occurs get medical attention. If inhaled remove victim to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or physician. If swallowed immediately call a POISON CENTER or physician. Do NOT induce vomiting. Rinse mouth. In case of fire use CO2, dry chemical, or foam for extinction.

14% of the mixture consists of ingredient(s) of unknown toxicity

Storage: Store locked up. Store in a well-ventilated place. Keep cool.

Disposal: Dispose of contents/container to an approved waste disposal plant.

IMPORTANT: Designed to be mixed with other components. Mixture will have hazards of all components. Before opening packages, read all warning labels. Follow all precautions.

Caution: All floor coatings may become slippery when wet. Where non-skid characteristics are desired, a small amount of clean sand may be added. Stir often during application.

This document represents hazards of the product referenced above. Refer to the individual Safety Data Sheet for hazards of the specific product you will be using.

KEEP OUT OF REACH OF CHILDREN FOR PROFESSIONAL USE ONLY

Refer to Safety Data Sheet for additional health and safety information.